

Reserve Funding Analysis

Full Reserve Study

for

Avalon at Cypress Community Association, Inc.

November 26, 2023





Reserve Funding Analysis

Full Reserve Study

for

Avalon at Cypress Community Association, Inc.

Table of Contents

| Pages | Subject |
|----------|---------------------------|
| 1 | Report Cover Sheet |
| 2 | Table of Contents |
| 3 to 28 | Reserve Study Summary |
| 29 to 39 | Reserve Item Summary |
| 40 to 44 | Reserve Item Listing |
| 45 to 46 | Cash Flow |
| 47 to 48 | Dues Summary |
| 49 to 56 | Revenue Report |
| 57 to 62 | Expense Report |
| 63 to 68 | Expense Summary |
| | |



November 26, 2023

Ms. Ashley Wiggins Taylor Morrison of Texas, Inc. 2929 Briarpark Drive, Suite 400 Houston, Texas 77042

Subject: Avalon at Cypress Community Association, Inc.

Dear Ms. Wiggins:

Great Boards, LLC is pleased to present to Avalon at Cypress Community Association, Inc. its requested full reserve study.

The following is a summary of the Avalon at Cypress Community Association, Inc. full reserve study report:

Project Description

Avalon at Cypress is a proposed 1,398 lot single-family home community under development in Cypress, Harris County, Texas.

The Avalon at Cypress Community Association maintains common area components including perimeter masonry walls, entry monument signage, cluster mailbox units, a clubhouse with a catering kitchen, meeting room and restrooms, a tot lot with traditional and "Nature Play" equipment, firepit, tennis and pickleball courts, swimming pool, common area irrigation equipment and lake fountains.

Unless otherwise stated, we have used 2023 as the placed-in-service year for all components.

Depth of Study

Full Service Reserve Study with Field Inspection A field inspection was made to visually verify the existing component conditions and to visually verify existing component quantities. In place testing, laboratory testing, and non-destructive testing of the reserve study components were not performed. Field measurements of some components were made to either verify improvement plan take offs or determine directly the quantities of a component. Photographs were taken of some of the site improvements.

Date of Physical Inspection

Avalon at Cypress Community Association, Inc. was physically inspected by Great Boards, LLC on September 08, 2023.

Fiscal Year

This reserve study was prepared for the fiscal year beginning January 1, 2024 and ending December 31, 2024.

Avalon at Cypress Community Association, Inc. Funding Study Summary - Continued

Initial Reserves

Initial reserves for this Reserve Study were estimated to be \$ 288,084 on December 31, 2023. Based upon a study start date of January 1, 2024 a total of 1 days of accrued interest at 0.20 percent per annum were compounded to yield an initial reserve balance of \$ 288,183.

Inflation Estimate

Inflation for the last year has been reviewed and a best estimate of the expected inflation for 2023 has been used to inflate future expenses.

Reserve Funding Goal

The reserve fund is set to be as close to fully funded as possible on an annual basis.

Summary of Financial Assumptions

The below table contains a partial summary of information provided by client for the Avalon at Cypress Community Association, Inc. reserve funding study.

| Reserve Study by Calendar Year Starting | January 1, 2024 |
|---|-----------------|
| Funding Study Length | 30 Years |
| Number of Dues Paying Members | 1398 |
| Initial Reserves ¹ | \$ 288, 183 |
| Annual Inflation Rate | 3.40% |
| Tax Rate on Reserve Interest ² | 30.00% |
| Minimum Reserve Account Balance | \$ O |
| Dues Change Period | 9 Years |
| Annual Operating Budget | \$0 |

¹ See Appendix A

² Taxed as an IRS exempt association

Reserve Study Assumptions

The below-listed assumptions are implicit in this reserve study:

- Cost estimates and financial information are accurate and current
- No unforeseen circumstances will cause a significant reduction of reserves
- Sufficient comprehensive property insurance exists to protect from insurable risks
- The Association plans to continue to maintain the existing common areas and amenities
- Reserve payments occur at the end of every calendar month
- Expenses occur at the end of the expense year.

Impact of Component Life

The projected life expectancy of the major components and the Association's reserve funding needs are closely tied. Performing the appropriate routine maintenance for each major component generally increases component useful life, effectively moving the component expense into the future, which reduces the Association's reserve funding payments. Failure to perform such maintenance can shorten the remaining useful life of major components, bringing the replacement expense closer to the present, and increasing the Association's reserve funding payments.

Financial Condition of Association

Reserve account balances and interest rate reported by Association as of July 31, 2023; plus remaining budgeted 2023 reserves contributions.

Avalon at Cypress Community Association, Inc. Funding Study Summary - Continued

Special Assessments

A special assessment is not indicated during the 30-year scope of this reserve study.

Study Method

In this study, we have used the "component" method because it is the only method which allows scrutiny of the funding details. The method is pragmatic, and allows human judgment and experience to enter into the equation.

Unless otherwise noted, the present cost of every reserve item in this report has been estimated using national standards and modified by an area cost adjustment factor. Where possible, known costs have been used. In addition, every reserve item has been given an estimated remaining useful life, an estimated useful life when new, and has been cast into the future to determine the inflated cost.

Equal annual payments are calculated for each reserve item based upon a payment starting year and a payment ending year using the end of period payment method. Interest earned on accumulated reserve funds and taxes on the reserve interest are also calculated. Initial reserve funds are consumed as expenses occur until fully depleted, reducing annual reserve payments to a minimum.

Summary of Findings

Great Boards, LLC has estimated future projected expenses for Avalon at Cypress Community Association, Inc. based upon preservation of existing improvements.

The attached funding study is limited in scope to those expense items listed in the attached "Avalon at Cypress Community Association, Inc. Reserve Study Expense Items". Expense items which have an expected life of more than 30 Years are not included in this reserve study unless payment for these long lived items occurs within the 30 Years of the reserve study envelope.

Of primary concern is the preservation of a positive funding balance with funds sufficient to meet projected expenses throughout the study life. Based upon the attached funding study, it is our professional opinion that member monthly fees as shown in the attached "Avalon at Cypress Community Association, Inc. Dues Summary" will realize this goal. Some reserve items in the "Avalon at Cypress Community Association, Inc. Revenue Summary Table" may not contain payments. In this analysis the initial reserves were used to make annual payments for expense items in their order of occurrence until the initial reserve was consumed. As a result reserve items without payments may be expected, particularly in the first few years of the funding study. Reserve items that have been paid with initial reserve funds are identified with a [FP] in the Expense Items Sheets. An item marked [PR] is partially paid with initial reserve funds.

Reserve Funding Status

Funding positions for reserve accounts generally fall into three categories. Reserves balances that fall between zero and 30% are considered "weak" as the special assessment probability of 26 to 53% is high. The second category is reserves within the 30 to 70% range. This funding position is classified as "fair" as the projected special assessment requirement is in the 3.50 to 17.60% range. When a funding position is referred to as "strong," reserves are between 70 and 100%, the risk of special assessment drops to between 2.40 and 1%.

By following the recommended payment plan, as of December 31, 2024, reserves for Avalon at Cypress Community Association, Inc. will be at an estimated 443.2% funding level. Accordingly, reserves for Avalon at Cypress Community Association, Inc. are anticipated to be strong, and by following the recommended funding plan, the Association will have adequate funds to meet projected repair and replacement expenses.

Percent Funded

Many reserve studies use the concept of "percent funded" to measure the reserve account balance against a theoretically perfect value. Percent funded is often used as a measure of the "financial health" of an association. The assumption is, the higher the percentage, the greater the "financial health". The question of substance is simply: "how much is enough?"

To answer the question, some understanding of percent funded is required. Percent funded is the ratio of current cash reserves divided by the fully funded value at any instant in time. Fully funded is defined as the future value, multiplied by the number of years used, divided by the expected life for the sum of all reserve items. In essence, fully funded is simply the total of the average net present value of the

Avalon at Cypress Community Association, Inc. Funding Study Summary - Continued

association improvements. Percent funded is then, the current reserve balance divided by the fully funded value multiplied by 100 (to give a percentage). The concept is useful when the reserve study is comprehensive, but misleading when the reserve study is superficial or constrained. As a result, we recommend that the statement "percent funded" be used with caution.

Keeping Your Reserve Study Current

Great Boards, LLC believes that reserves funding studies are an essential part of community management. Property constantly changes and evolves, and as a result, the useful life of a reserves funding study is at best a few years, and certainly not more than five years. Accordingly, this reserve study should be updated:

- At changes in interest rates
- At changes in inflation rates
- At changes in the number of dues paying members
- Before starting new improvements
- Before making changes to the property
- After a flood or fire
- After the change of ownership or management
- After annexation or incorporation.

Items Beyond the Scope of this Report

Items beyond the scope of this report include:

- Building or land appraisals for any purpose
- State or local zoning ordinance violations
- Building code violations
- Soils conditions, soils contamination or geological stability of site
- Engineering analysis or structural stability of site
- Air quality, asbestos, electromagnetic radiation, formaldehyde, lead, mercury, radon, water quality or other environmental hazards
- Invasions by pests, termites and any or all other destroying organisms, insects, birds, bats or animals to buildings or site--this study is not a pest inspection
- Adequacy or efficiency of any system or component on site
- Specifically excluded reserve items
- Septic systems and septic tanks
- Buried or concealed portions of swimming pools, pool liners, Jacuzzis and spas or similar items
- · Items concealed by signs, carpets or other things are also excluded from this study
- Missing or omitted information supplied by client for the purposes of reserve study preparation
- Hidden improvements such as sewer lines, water lines, irrigation lines or other buried or concealed items.

Statement of Qualifications

Kerry-Lynn Goto of Great Boards, LLC is a professional in the business of preparing reserve studies for common interest developments and is familiar with construction practices, construction costs, and contracting practices. The preparer of this reserve study is a CAI-certified Reserve Study Specialist.

Conflict of Interest

As the preparer of this reserve study, Great Boards, LLC certifies that it does not have any vested interests, financial interests, or other interests that would cause a conflict of interest in the preparation of this reserve study. This reserve study is a reflection of information provided to the reserve study preparer and created for the Association's use, not for the purpose of an audit, background checks of historical records, or forensic/quality analyses. Any on-site inspection is not a project audit or quality inspection.

Avalon at Cypress Community Association, Inc. Funding Study Summary - Continued

Great Boards, LLC thanks you for the opportunity to be of service in the preparation of the attached reserve study. Please feel free to contact us by telephone at (602) 569-0288, or by email at info@greatboards.com with any questions.

Berry Aym boto

Kerry-Lynn Goto, RS

Avalon at Cypress Community Association, Inc. Funding Study Summary - Continued

Enclosures:

18 Pages of Photographs Attached APPENDIX "A" - Summary of Reserve Accounts



Appliances & Electronics - Ice-maker



Appliances & Electronics - Refrigerator-freezer



Appliances & Electronics - Access controller




Appliances & Electronics - Fire alarm panel

Avalon at Cypress Community Association, Inc. Funding Study Summary - Continued



Appliances & Electronics - Observation camera



Appliances & Electronics - Typical television

Avalon at Cypress Community Association, Inc. Funding Study Summary - Continued



Drainage & Irrigation - Stormwater pond



Drainage & Irrigation - Backflow preventer



Drainage & Irrigation - Irrigation controller



Fences & Walls - Chain-link fencing

Avalon at Cypress Community Association, Inc. Funding Study Summary - Continued




Fences & Walls - Metal fencing



Fences & Walls - Typical perimeter masonry wall


Avalon at Cypress Community Association, Inc. Funding Study Summary - Continued



Furniture - Typical clubhouse



Furniture - Lifeguard chair





Furniture - Typical park bench



Furniture - Typical pool area

Avalon at Cypress Community Association, Inc. Funding Study Summary - Continued



Furniture - Typical shade covers




HVAC & Plumbing - Air-conditioners

Avalon at Cypress Community Association, Inc. Funding Study Summary - Continued



HVAC & Plumbing - Drinking fountain



HVAC & Plumbing - Water heater

Avalon at Cypress Community Association, Inc. Funding Study Summary - Continued



HVAC & Plumbing - Firepit



Lake - Lake fountain

Avalon at Cypress Community Association, Inc. Funding Study Summary - Continued



Lighting - Typical bollard fixture



Lighting - Typical pole-mounted fixture

Avalon at Cypress Community Association, Inc. Funding Study Summary - Continued



Mailboxes & Signage - Typical cluster mailboxes



Mailboxes & Signage - Entry monument signage



Avalon at Cypress Community Association, Inc. Funding Study Summary - Continued

Painting & Repairs - Typical clubhouse interior



Painting & Repairs - Clubhouse entryway pavers



Pool - Typical Kool-deck surface




Pool - Swimming pool

Avalon at Cypress Community Association, Inc. Funding Study Summary - Continued



Roofing - Typical metal roofing



Roofing - Typical roof gutter and downspout

Avalon at Cypress Community Association, Inc. Funding Study Summary - Continued



Sports Courts - Pickleball court



Sports Courts - Tennis court

Avalon at Cypress Community Association, Inc. Funding Study Summary - Continued



Tot Lot - "Nature Play" components



Tot Lot - Play platform



Avalon at Cypress Community Association, Inc. Funding Study Summary - Continued

Tot Lot - Swing-set

Avalon at Cypress Community Association, Inc. Funding Study Summary - Continued

Summary of Reserve Accounts Account Description Amount Interest Rate Statement Date December 31, 2023 Remaining 2023 Budgeted Reserves Contributions \$171,600.00 .20% Capital Reserve Cash-CIT \$16,484.14 .20% July 31, 2023 Capital Reserve Cash-New Management \$100,000.00 .20% July 31, 2023

\$99.27

.20%

\$ 288,183.41

January 1, 2024

January 1, 2024

APPENDIX "A"

Initial reserve balances have been provided by client and have not been audited for use in this report.

Reserve Values Used :

Reserve Account Total Earned Interest

Evaluation of Initial Reserve Account:

Reserve account balances and interest rate reported by Association as of July 31, 2023; plus remaining budgeted 2023 reserves contributions.

Initial reserve funds are contained in 3 separate funding accounts. The future value of each account was calculated based upon the account interest rate and the number of elapsed days until the study start date (January 1, 2024). The future value of the accounts was totaled and the interest rates were blended to yield a weighted average interest rate of 0.20%. The implicit assumption has been made that the reserve accounts were not drawn down between the date of the known reserve balance and the study start date.

Avalon at Cypress Community Association, Inc. Reserve Study Expense Item Summary

| Reserve Items | Current Cost When New | Estimated Remaining Life | Expected Life When New | First Replacement Cost | Raw Annual Payment | Repeating Item? |
|---|--------------------------|-----------------------------|---------------------------|------------------------------|-----------------------|--------------------|
| | | Appliances | & Electronics | | 1 | |
| (D) Appliances Ice-maker Replacement | \$ 2,800 | 14 Years | 15 Years | \$ 4,659 | \$ 306 | Yes |
| (D) Appliances Refrigerator- freezer Replacement | \$ 4,200 | 14 Years | 15 Years | \$ 6,989 | \$ 459 | Yes |
| (D) Electronics Access Control System Allowance | \$ 5,000 | 4 Years | 5 Years | \$ 5,925 | \$ 1,179 | Yes |
| (D) Electronics Fire Control Panel Replacement | \$ 1,800 | 11 Years | 12 Years | \$ 2,705 | \$ 223 | Yes |
| (D) Electronics Observation Cameras Allowance | \$ 1,000 | 4 Years | 5 Years | \$ 1,185 | \$ 236 | Yes |
| (D) Electronics Televisions Replacement | \$ 2,300 | 9 Years | 10 Years | \$ 3,230 | \$ 320 | Yes |
| | | Drainage | & Irrigation | | | |
| (D) Drainage Stormwater Management Allowance | \$ 20,000 | 14 Years | 15 Years | \$ 33,282 | \$ 2,186 | Yes |
| (D) Irrigation Backflow Preventers Replacement | \$ 4,400 | 9 Years | 10 Years | \$ 6,179 | \$ 612 | Yes |
| (D) Irrigation Controllers Allowance | \$ 2,000 | 11 Years | 12 Years | \$ 3,006 | \$ 248 | Yes |
| | | Fences | & Walls | | | |
| (D) Fences Chain-link Replacement | \$ 14,820 | 29 Years | 30 Years | \$ 41,040 | \$ 1,327 | No |
| (D) Fences Metal Replacement | \$ 19,350 | 29 Years | 30 Years | \$ 53,584 | \$ 1,733 | Yes |
| (D) Walls Masonry Perimeter Allowance | \$ 3,000 | 9 Years | 10 Years | \$ 4,213 | \$ 417 | Yes |
| | | Fur | niture | | | |
| (D) Clubhouse Interior Allowance | \$ 5,945 | 9 Years | 10 Years | \$ 8,348 | \$ 827 | Yes |
| (D) Lifeguard Chair Replacement | \$ 950 | 6 Years | 7 Years | \$ 1,205 | \$ 171 | Yes |
| (D) Park Allowance | \$ 20,000 | 9 Years | 10 Years | \$ 28,085 | \$ 2,781 | Yes |
| (D) Pool Area Replacement | \$ 15,000 | 6 Years | 7 Years | \$ 19,024 | \$ 2,699 | Yes |
| (D) Shade Covers Replacement | \$ 21,096 | 7 Years | 8 Years | \$ 27,680 | \$ 3,433 | Yes |
| | | HVAC & | Plumbing | | | |
| (D) HVAC Air-Conditioners Replacement | \$ 21,000 | 9 Years | 10 Years | \$ 29,490 | \$ 2,920 | Yes |
| (D) Plumbing Drinking Fountain Replacement | \$ 1,500 | 24 Years | 25 Years | \$ 3,505 | \$ 137 | Yes |
| (D) Plumbing Firepit Assembly Allowance | \$ 5,000 | 4 Years | 5 Years | \$ 5,925 | \$ 1,179 | Yes |

| Reserve Items | Current Cost When New | Estimated Remaining Life | Expected Life When New | First Replacement Cost | Raw Annual Payment | Repeating Item? |
|---|--------------------------|-----------------------------|---------------------------|------------------------------|-----------------------|--------------------|
| (D) Plumbing Water Heater Replacement | \$ 2,100 | 9 Years | 10 Years | \$ 2,949 | \$ 292 | Yes |
| | | La | akes | | | |
| (D) Lake Fountains Replacement | \$ 24,000 | 6 Years | 7 Years | \$ 30,439 | \$ 4,318 | Yes |
| | | Lig | hting | | | |
| (D) Bollard Fixtures Replacement | \$ 7,500 | 24 Years | 25 Years | \$ 17,526 | \$ 684 | Yes |
| (D) Pole-Mounted Fixtures Replacement | \$ 6,240 | 9 Years | 10 Years | \$ 8,763 | \$ 868 | Yes |
| | | Mailboxe | s & Signage | | | |
| (D) Mailboxes Replacement | \$ 94,000 | 24 Years | 25 Years | \$ 219,663 | \$ 8,569 | Yes |
| (D) Signage Entry Monument Refreshment Allowance | \$ 5,000 | 9 Years | 10 Years | \$ 7,021 | \$ 695 | Yes |
| | | Painting | & Repairs | | | |
| (D) Painting Interior Clubhouse | \$ 3,500 | 7 Years | 8 Years | \$ 4,592 | \$ 570 | Yes |
| (D) Painting Metal Unfunded | \$ 0.00 | 35 Years | 35 Years | \$ 0 | \$ 0.00 | No |
| (D) Repairs Concrete & Pavers | \$ 2,000 | 9 Years | 10 Years | \$ 2,809 | \$ 278 | Yes |
| | | F | ool | | | - |
| (D) Chemical Controller Replacement | \$ 6,000 | 7 Years | 8 Years | \$ 7,872 | \$ 976 | Yes |
| (D) Filters Replacement | \$ 2,400 | 14 Years | 15 Years | \$ 3,994 | \$ 262 | Yes |
| (D) Kool-Deck Recoating | \$ 10,255 | 3 Years | 4 Years | \$ 11,747 | \$ 2,925 | Yes |
| (D) Kool-Deck Replacement | \$ 38,090 | 27 Years | 28 Years | \$ 98,554 | \$ 3,422 | Yes |
| (D) Pool Interior Refinishing | \$ 33,508 | 14 Years | 15 Years | \$ 55,760 | \$ 3,662 | Yes |
| (D) Pumps & Motors Replacement | \$ 2,400 | 4 Years | 5 Years | \$ 2,844 | \$ 566 | Yes |
| | | Refurt | bishment | | | |
| (D) Clubhouse Renovation | \$ 10,000 | 24 Years | 25 Years | \$ 23,368 | \$ 912 | Yes |
| | | Ro | ofing | | | |
| (D) Gutters & Downspouts Allowance | \$ 2,000 | 29 Years | 30 Years | \$ 5,538 | \$ 179 | No |
| (D) Metal Clubhouse Replacement | \$ 38,998 | 29 Years | 30 Years | \$ 107,992 | \$ 3,493 | No |
| | | Sport | s Courts | | | |
| (D) Pickleball & Tennis Courts Resurfacing | \$ 8,568 | 9 Years | 10 Years | \$ 12,032 | \$ 1,191 | Yes |

| Reserve Items | Current Cost When New | Estimated Remaining Life | Expected Life When New | First Replacement Cost | Raw Annual Payment | Repeating Item? |
|--|--------------------------|-----------------------------|---------------------------|------------------------------|-----------------------|--------------------|
| | | То | t Lot | | | |
| (D) Landing Surface Wood Mulch Unfunded | \$ 0.00 | 35 Years | 35 Years | \$ 0 | \$ 0.00 | No |
| (D) Nature Play Components Allowance | \$ 25,000 | 24 Years | 25 Years | \$ 58,421 | \$ 2,279 | Yes |
| (D) Play Platform Allowance | \$ 20,000 | 24 Years | 25 Years | \$ 46,737 | \$ 1,823 | Yes |
| (D) Swing-set Replacement | \$ 3,500 | 24 Years | 25 Years | \$ 8,179 | \$ 319 | Yes |

Avalon at Cypress Community Association, Inc. Funding Study Expense Item Summary - Continued

Raw Annual Payments do not include earned interest, tax adjustments or salvage.

Months Remaining in Calendar Year 2024: 12

Expected annual inflation: 3.40%

Interest earned on reserve funds: 0.20%

Initial Reserve: \$ 288,183

(D) Indicates Tabulated Reserve Item Description.

Reserve Item Descriptions

| Category | Reserve Item Name | Reserve Item Description |
|--------------------------|---|--|
| | Appliances Ice-maker Replacement | This component consists of: 1 - "GE" Profile series under-counter ice-maker, model UCC15NPRBII S/N HT223435 in the clubhouse kitchen. Funding for as-needed replacement has been included every 15 years. |
| | | Cost source: Internet research |
| Appliances & Electronics | Appliances Refrigerator- freezer Replacement | This component consists of: 1 - "GE" Cafe series stainless steel, French-door style refrigerator-freezer, model CVE28DP2NCS1 S/N DV502519 in the clubhouse kitchen. Funding for as-needed replacement has been included every 15 years. Cost source: Internet research |
| | Electronics Access Control System Allowance | A \$5,000 allowance has been included every 5 years for as-needed upgrades/enhancements to the "DSX" amenity area access system. Funding may be used for, but is not limimted to upgrades to and/or replacement of fob-readers and controller. Cost source: Allowance |

| Category | Reserve Item Name | Reserve Item Description |
|--------------------------|---|---|
| | | Funding has been included for as-needed replacement of the clubhouse fire control panel installed in the FACP room every 12 years: |
| | Electronics Fire Control Panel Replacement | 1 - Pottter IPA-100 addressable fire panel |
| | | Cost source: Internet research |
| | Electronics Observation Cameras Allowance | A \$1,000 allowance has been included every 5 years for as-needed replacement of amenity area observation cameras. |
| | | Cost source: Allowance |
| Appliances & Electronics | | This component consists of: |
| | | Patio: |
| | | 1 - 60" - "Apollo" outdoor television @ \$1,500 ea. |
| | Electronics Televisions Replacement | Clubhouse: |
| | | 1 - 65" - "Samsung" television @ \$800 ea. |
| | | Funding for as-needed replacement has been included every 10 years. |
| | | Cost source: Internet research |
| | Drainage Stormwater Management Allowance | For purposes of this report we have included a \$20,000 allowance on a 15-year cycle for as-needed repairs to the community's stormwater management system. |
| | | Cost source: Allowance |
| | | Funding has been included for replacement of: |
| Drainage & Irrigation | Irrigation Backflow Preventers | 4 - irrigation backflow preventers |
| | Replacement | on a 10-year cycle. |
| | | Cost source: AFI Database |
| | Irrigation Controllers Allowance | We have included funding in the amount of \$2,000 for as-needed replacement of common area irrigation timeclocks on a 12-year cycle. |
| | | Cost source: Allowance |

| Category | Reserve Item Name | Reserve Item Description |
|----------------|--------------------------------------|--|
| | | Funding has been included for one-time replacement of the sports courts fencing and gates has been included at the 30-year mark. For inventory purposes, this component consists of: |
| | | Pi // hall a surface |
| | | Pickleball courts: 388 - lin. ft. of 8' high vinyl-coated chain link fencing with 1 - 8' x 4' gate @ \$15.00 |
| | Fences Chain-link Replacement | lin. ft. |
| | | Tennis court: |
| | | 360 - lin. ft. of 10' high vinyl-coated chain link fencing with 1 - 10' x 4' gate @ \$25.00 lin. ft. |
| Fences & Walls | | Cost source: AFI Database |
| | | This component consists of the following pool-area metal fencing and gates: |
| | Fences Metal Replacement | 430 lin. ft. of 6' high mesh-style, powder-coated metal fencing with 3 gates @ \$45.00 lin. ft. |
| | | Replacement funding has been included on a 30-year cycle. |
| | | Cost source: AFI Database |
| | Walls Masonry Perimeter Allowance | A \$3,000 allowance has been included every 10 years for as-needed repairs to perimeter masonry walls. |
| | | Cost source: Allowance |
| | | The following clubhouse interior furniture was inventoried during our September 8, 2023 site visit: |
| | | 4 - counter-height bar-stools with padded seats and backs @ \$200 ea. |
| | Olubbarra Interior Allemana | 7 - 60" round foldable laminate tables @ \$175 ea. |
| | Clubhouse Interior Allowance | 56 - stackable side chairs with padded seats and backs @ \$70 ea. |
| Furniture | | Funding for as-needed replacement has been included every 10 years. |
| | | Cost source: Internet research |
| | | This component consists of: |
| | Lifeguard Chair Replacement | 1 - composite lifeguard chair |
| | | at the pool area, with replacement funding every 7 years. |
| | | Cost source: Internet research |

| Category | Reserve Item Name | Reserve Item Description |
|-----------|-----------------------|--|
| | | The following furniture was inventoried during our September 8, 2023 site visit: |
| Furniture | Park Allowance | The following furniture was inventoried during our September 8, 2023 site visit: 11 - 6' metal benches with back 4 - composite (red) benches without back 8 - composite Adirondack-style chairs 1 - metal bicycle rack 2 - 8' metal brunch tables 2 - 7' metal benches without back 26 - metal brunch chairs 3 - 48" square metal brunch tables 3 - loveseats with cushions 6 - club chairs with cushions 4 - rectangular metal coffee tables 4 - round metal tea tables 8 - metal trash receptacles A \$20,000 funding allowance has been included every 10 years for as-needed replacement. |
| | | Cost source: Allowance |
| | | The following pool-area furniture was inventoried during our September 8, 2023 site visit: |
| | Pool Area Replacement | 39 - sling-style chaise lounges without arms 12 - 16" round metal tea tables 5 - 42" - round metal brunch tables 20 - sling-style brunch chairs 6 - child-size brunch chairs 9 - composite in-water chaise lounges 9 - fabric market umbrellas (in storage room) 2 - metal trash receptacles A \$15,000 funding allowance for as-needed replacement has been included every 7 years. |

| Category | Reserve Item Name | Reserve Item Description |
|-----------------|--|--|
| | | The following fabric shade covers were inventoried during our September 8, 2023 site visit: |
| | | Pool area: 1,038 sq. ft. fabric shade covers |
| Furniture | Shade Covers Replacement | Tot lot: 720 sq. ft. fabric shade covers |
| | | Funding for as-needed replacement has been included every 8 years. |
| | | Cost source: Internet research |
| | | This component consists of: |
| | | 2 - "Trane" model 4TTR060/100BA 5-ton heat pump units, @ \$7,500 ea. S/N 22303HMUHF |
| | | S/N 22302J8FHF |
| | HVAC Air-Conditioners Replacement | 1 - "Trane" model 4TTR402N100AA 3.5-ton heat pump unit @ \$6,000 ea. S/N 22311TT15F |
| | | serving the clubhouse. Funding for as-needed replacement has been included every 10 years. |
| | | Cost source: Internet research |
| | | This component consists of: |
| HVAC & Plumbing | Plumbing Drinking Fountain | 1 - "Elkay" Hi-Low, stainless-steel, chilled drinking fountain with bottle filler |
| | Replacement | at the patio area. Funding for as-needed replacement has been included every 25 years. |
| | | Cost source: elkay.com |
| | Plumbing Firepit Assembly Allowance | A \$5,000 funding allowance has been included every 5 years for as-needed replacement of the firepit's gas assembly. |
| | | Cost source: Allowance |
| | | This component funds for as-needed replacement of the clubhouse water heater every 10 years: |
| | Plumbing Water Heater Replacement | 1 - "AO Smith" model DEL 30 200 electric water heater with expansion tank |
| | | This water heater is installed in the clubhouse FACP room. |
| | | Cost source: Internet research |

| Category | Reserve Item Name | Reserve Item Description |
|---------------------|---|--|
| | | Funding has been included for replacement of: |
| Lakes | Lake Fountains Replacement | 2 - lake fountains |
| | | every 7 years. |
| | | Cost source: Client |
| | | Funding has been included for as-needed replacement of: |
| | | Parking lot: |
| | | 7 - bollard-style lighting fixtures |
| | Bollard Fixtures Replacement | Pool area: |
| | | 8 - bollard-style lighting fixtures |
| | | every 25 years. |
| Lighting | | Cost source: lampsplus.com |
| | | Funding has been included for replacement of the following parking lot and amenity area lighting: |
| | Dela Maustad Fisturas | 13 - pole-mounted LED light fixtures |
| | Pole-Mounted Fixtures Replacement | every 10 years. Cost indicated is for replacement of fixtures only, as the poles and mounting brackets should last the life of the project with routine cleaning maintenance. |
| | | Cost source: AFI Database |
| | | For purposes of this report we have assumed replacement of: |
| | | 46 - 16 mailbox plus 2 package box units |
| | Mailboxes Replacement | 1 - 8 mailbox plus 1 package box unit |
| Mailboxes & Signage | | on a 25-year cycle. |
| | | Cost source: Client |
| | Signage Entry Monument Refreshment Allowance | For purposes of this report we have included a \$5,000 funding allowance on a 10- year cycle for as-needed refreshment of the community's two entry monument structures. |
| | | Cost source: Allowance |

| Category | Reserve Item Name | Reserve Item Description |
|--------------------|-----------------------------|--|
| | Painting Interior Clubhouse | A \$3,500 in funding allowance has been included for as-needed painting of the clubhouse interiors and pool-area restrooms every 8 years. |
| | | Cost source: Advanced Painting & Contracting |
| Painting & Repairs | Painting Metal Unfunded | The metal fencing and gates at the pool area and the light poles appear to be powder-coated. No painting maintenance should be required. |
| | Repairs Concrete & Pavers | Funding in the amount of \$2,000 has been included for as-needed repairs to the concrete flatwork and parking lot at the recreation area, and the pavers at the clubhouse entryway every 10 years. |
| | | Cost source: Allowance |
| | | For purposes of this report we have assumed the following chemical controller with replacement funding every 8 years: |
| | Chemical Controller | 1 - "Hayward" model CAT 5000 chemical controller, with 2 injector pumps |
| | Replacement | We did not have access to the pool equipment during our September 8, 2023 site visit. This component should be verified during the next reserve study site visit. |
| | | Cost source: Allied Pool |
| | | For purposes of this report, we have assumed replacement funding on a 15-year cycle for: |
| | Filters Replacement | 2 - "Pentair" Triton II model TR-140 high-rate sand filters |
| Pool | | We did not have access to the pool equipment during our September 8, 2023 site visit. This component should be verified during the next reserve study site visit. |
| | | Cost source: AFI Database |
| | | Funding has been included for recoating of the pool-area Kool-deck surface on a 4-year cycle. |
| | Kool-Deck Recoating | For inventory purposes, this surface area is approximately 5,860 sq. ft. |
| | | Cost source: Allied Pool |
| | | Funding has been included for replacement of the pool-area Kool-deck surface on a 28-year cycle. |
| | Kool-Deck Replacement | For inventory purposes, this surface area is approximately 5,860 sq. ft. |
| | | Cost source: Allied Pool |

Avalon at Cypress Community Association, Inc. Funding Study Expense Item Summary - Continued

| Category | Reserve Item Name | Reserve Item Description |
|---------------|---|--|
| | | This component funds for resurfacing of the swimming pool interior every 15 years: |
| | Pool Interior Refinishing | 6,335 - sq. ft. plaster resurfacing @ \$4.50 sq. ft. \$5,000 allowance for waterline and trim tile |
| | | Cost source: Allied Pool For purposes of this report, we have assumed replacement funding for: |
| Pool | Pumps & Motors Replacement | 2 - "Pentair" WhisperFlo 3.0 HP pool pumps @ \$1,200 ea. We did not have access to the pool equipment during our September 8, 2023 site |
| | | visit. This component should be verified during the next reserve study site visit. |
| Refurbishment | Clubhouse Renovation | A \$10,000 funding allowance has been included for remodeling of the clubhouse interior and pool-area restrooms on a 25-year cycle. This remodeling includes "as needed" replacement of plumbing fixtures, flooring, wall coverings, lockers, lighting, ceiling fans, doors and the pool-area shower. |
| | | Cost source: Allowance |
| | Gutters & Downspouts Allowance | A one-time \$2,000 allowance has been included for as-needed replacement of clubhouse roof gutters and downspouts in conjunction with metal roof replacement at year 30. |
| | | Cost source: Allowance |
| Roofing | | The clubhouse metal roof should last the life of the project. However, as a precaution, we have included one-time replacement funding at year 30: |
| | Metal Clubhouse Replacement | 4,105 sq. ft. standing seam metal roofing |
| | | Cost source: National Construction Estimator |
| | | Funding for as-needed resurfacing of the community's (2) pickleball and (1) tennis courts has been included every 10 years: |
| Sports Courts | Pickleball & Tennis Courts Resurfacing | 1,736 - sq. ft. of coated concrete court surface |
| | | Cost source: AFI Database |
| Tot Lot | Landing Surface Wood Mulch Unfunded | Funding has been excluded for replenishment of the wood mulch landing surface at the tot lot. As-needed replenishment should be performed under the Association's annual operating budget. |

Avalon at Cypress Community Association, Inc. Funding Study Expense Item Summary - Continued

| Category | Reserve Item Name | Reserve Item Description |
|----------|-------------------------------------|---|
| | | This component consists of the following National Wildlife Federation "Nature Play" equipment at the community's tot lot: |
| | Nature Play Components Allowance | 1 - "Kompan" set of log balance beams 1 - "Kompan" see-saw 1 - "Kompan" spinner |
| | | A \$25,000 allowance has been included every 25 years for as-needed replacement of these components. |
| | | Cost source: Allowance |
| | | This component consists of: |
| Tot Lot | Play Platform Allowance | 1 - small-sized "Kompan" play platform |
| | | at the lot. Funding for as-needed replacement has been included every 25 years. |
| | | Cost source: Allowance |
| | | This component consists of: |
| | | 1 - A-frame swing-set with 1-bucket and 2-strap seats |
| | Swing-set Replacement | located at the tot lot. Funding for as-needed replacement has been included on a 25-year cycle. |
| | | Cost source: Bluegrass Playgrounds, Inc. |

Avalon at Cypress Community Association, Inc. Funding Study Expense Item Summary - Continued

Avalon at Cypress Community Association, Inc. Reserve Study Expense Item Listing

| Reserve Items | Unit Cost | No Units | Current Cost When New | Estimated Remaining Life | Expected Life When New | Calendar Year | Estimated Future Cost | Raw Annual Payment | |
|-------------------------------------|-------------------|----------|--------------------------------|--------------------------------|---------------------------------|------------------|-----------------------------|--------------------------|--|
| | | L | Applianc | es & Electron | lics | | 1 1 | | |
| Appliances Ice- | \$ 2,800 ea | 1 | \$ 2,800 | 14 Years | 15 Years | 2038 | \$ 4,659 | \$ 306.02 | |
| maker Replacement | ψ 2,000 ea | | φ 2,000 | 15 Years | 15 Teals | 2053 | \$ 7,754 | \$ 509.25 | |
| Appliances | \$ 4,200 ea | | | 14 Years | | 2038 | \$ 6,989 | \$ 459.03 | |
| Refrigerator-freezer Replacement | | 1 | \$ 4,200 | 15 Years | 15 Years | 2053 | \$ 11,631 | \$ 763.87 | |
| | | | | 4 Years | | 2028 | \$ 5,925 | \$ 1,179.20 | |
| | | | | | | 2033 | \$ 7,021 | \$ 1,397.38 | |
| Electronics Access | Ф. г . 000 | | \$ 5,000 | | | 2038 | \$ 8,320 | \$ 1,655.92 | |
| Control System Allowance | \$ 5,000 ea | 1 | | 5 Years | 5 Years | 2043 | \$ 9,860 | \$ 1,962.30 | |
| | | | | | | 2048 | \$ 11,684 | \$ 2,325.37 | |
| | | | | | | 2053 | \$ 13,846 | \$ 2,755.61 | |
| Electronics Fire | | 1 | \$ 1,800 | 11 Years | | 2035 | \$ 2,705 | \$ 222.77 | |
| Control Panel | \$ 1,800 ea | | | 10 \/a are | 12 Years | 2047 | \$ 4,066 | \$ 334.80 | |
| Replacement | | | | 12 Years | | 2059 | \$ 6,111 | \$ 503.19 | |
| | | | | 4 Years | | 2028 | \$ 1,185 | \$ 235.84 | |
| | | | | | | 2033 | \$ 1,404 | \$ 279.48 | |
| Electronics | \$ 1,000 ea | 1 | \$ 1,000 | 5 Years | 5 Vooro | 2038 | \$ 1,664 | \$ 331.18 | |
| Observation Cameras Allowance | | | | | 5 Years | 2043 | \$ 1,972 | \$ 392.46 | |
| | | | | | | 2048 | \$ 2,337 | \$ 465.07 | |
| | | | | | | 2053 | \$ 2,769 | \$ 551.12 | |
| Electronics | | | | 9 Years | | 2033 | \$ 3,230 | \$ 319.79 | |
| Televisions | \$ 2,300 ea | 1 | \$ 2,300 | 10 \/a are | 10 Years | 2043 | \$ 4,536 | \$ 449.07 | |
| Replacement | | | | 10 Years | | 2053 | \$ 6,369 | \$ 630.62 | |
| | | | Draina | ge & Irrigatio | n | | | | |
| Drainage Stormwater | | | | 14 Years | | 2038 | \$ 33,282 | \$ 2,185.86 | |
| Management Allowance | \$ 20,000 ea | 1 | \$ 20,000 | 15 Years | 15 Years | 2053 | \$ 55,384 | \$ 3,637.47 | |
| Irrigation Backflow | | | | 9 Years | | 2033 | \$ 6,179 | \$ 611.77 | |
| Preventers | \$ 1,100 ea | 4 | \$ 4,400 | | 10 Years | 2043 | \$ 8,677 | \$ 859.10 | |
| Replacement | | | | 10 Years | | 2053 | \$ 12,184 | \$ 1,206.40 | |
| Irrigation Controllers | | | | 11 Years | | 2035 | \$ 3,006 | \$ 247.52 | |
| | \$ 2,000 ea | 1 | \$ 2,000 | | 12 Years | 2047 | \$ 4,518 | \$ 372.00 | |
| Allowance | | | | 12 Years | | 2059 | \$ 6,790 | \$ 559.10 | |

| Reserve Items | Unit Cost | No Units Current Cost When New | | Estimated Remaining Life | Expected Life When New | Calendar Year | Estimated Future Cost | Raw Annual Payment |
|----------------------------------|----------------------------|---|-----------|--------------------------------|---------------------------------|----------------------|-----------------------------|----------------------------|
| | | | Fen | ces & Walls | | | | |
| Fences Chain-link Replacement | \$ 14 820 ea 1 | | \$ 14,820 | 29 Years | 30 Years | 2053 | \$ 41,040 | \$ 1,327.47 |
| Fences Metal Replacement | \$ 45.00 / If | 430 lf | \$ 19,350 | 29 Years | 30 Years | 2053 | \$ 53,584 | \$ 1,733.23 |
| Walls Masonry | ¢ 0.000 | | ¢ 0.000 | 9 Years | 40.1/2 2 | 2033 | \$ 4,213 | \$ 417.12 |
| Perimeter Allowance | \$ 3,000 ea | 1 | \$ 3,000 | 10 Years | 10 Years | 2043 2053 | \$ 5,916 \$ 8,308 | \$ 585.75 \$ 822.55 |
| | | | E | urniture | | | | |
| | | | • | 9 Years | | 2033 | \$ 8,348 | \$ 826.59 |
| Clubhouse Interior Allowance | \$ 5,945 ea | 1 | \$ 5,945 | 10 Years | 10 Years | 2000 2043 2053 | \$ 11,723 \$ 16,463 | \$ 1,160.76 \$ 1,630.02 |
| | | | | 6 Years | | 2033 | \$ 1,205 | \$ 170.94 |
| | | | \$ 950 | 0 Teals | | 2030 | \$ 1,528 | \$ 216.80 |
| Lifeguard Chair Replacement | \$ 950 ea | 1 | | | 7 Years | 2007 | \$ 1,938 | \$ 274.96 |
| | , | | | 7 Years | , rouro | 2051 | \$ 2,458 | \$ 348.72 |
| | | | | | | 2058 | \$ 3,117 | \$ 442.28 |
| | | | | 9 Years | | 2033 | \$ 28,085 | \$ 2,780.79 |
| Park Allowance | \$ 20,000 ea | 1 | \$ 20,000 | 10 Years | 10 Years | 2043 | \$ 39,440 | \$ 3,904.98 |
| | | | | | | 2053 | \$ 55,384 | \$ 5,483.66 |
| | | | | 6 Years | | 2030 | \$ 19,024 | \$ 2,698.99 |
| | | | | | | 2037 | \$ 24,128 | \$ 3,423.09 |
| Pool Area Replacement | \$ 15,000 ea | 1 | \$ 15,000 | 7.)/ | 7 Years | 2044 | \$ 30,601 | \$ 4,341.44 |
| Replacement | | | | 7 Years | | 2051 | \$ 38,811 | \$ 5,506.17 |
| | | | | | | 2058 | \$ 49,223 | \$ 6,983.38 |
| | | | | 7 Years | | 2031 | \$ 27,680 | \$ 3,432.64 |
| Shade Covers | ¢ 10 00 / #2 | 1750 #2 | ¢ 04 000 | | 0 Vac | 2039 | \$ 36,318 | \$ 4,503.91 |
| Replacement | \$ 12.00 / ft ² | 1758 ft ² | \$ 21,096 | 8 Years | 8 Years | 2047 | \$ 47,652 | \$ 5,909.50 |
| | | | | | | 2055 | \$ 62,524 | \$ 7,753.75 |
| | | | Ηνα | & Plumbing | | | | |
| HVAC Air- | | | | 9 Years | | 2033 | \$ 29,490 | \$ 2,919.83 |
| Conditioners | \$ 21,000 ea | 1 | \$ 21,000 | 10 Years | 10 Years | 2043 | \$ 41,412 | \$ 4,100.23 |

| Reserve Items | | | No Units Cost When New | | Expected Life When New | Calendar Year | Estimated Future Cost | Raw Annual Payment |
|-------------------------------|--------------|----|---------------------------------|--------------|---------------------------------|------------------|-----------------------------|--------------------------|
| HVAC Air- | \$ 21,000 ea | 1 | \$ 21,000 | 10 Years | 10 Years | 2053 | \$ 58,153 | \$ 5,757.84 |
| Plumbing Drinking Fountain | \$ 1,500 ea | 1 | \$ 1,500 | 24 Years | 25 Years | 2048 | \$ 3,505 | \$ 136.75 |
| Replacement | | | | 25 Years | | 2073 | \$ 8,191 | \$ 319.55 |
| | | | | 4 Years | | 2028 | \$ 5,925 | \$ 1,179.20 |
| | | | | | | 2033 | \$ 7,021 | \$ 1,397.38 |
| Plumbing Firepit Assembly | \$ 5,000 ea | 1 | \$ 5,000 | | 5 Years | 2038 | \$ 8,320 | \$ 1,655.92 |
| Allowance | \$ 5,000 ea | I | φ 5,000 | 5 Years | 5 10015 | 2043 | \$ 9,860 | \$ 1,962.30 |
| | | | | | | 2048 | \$ 11,684 | \$ 2,325.37 |
| | | | | | | 2053 | \$ 13,846 | \$ 2,755.61 |
| Plumbing Water | | | | 9 Years | | 2033 | \$ 2,949 | \$ 291.98 |
| Heater | \$ 2,100 ea | 1 | \$ 2,100 | 10 Years | 10 Years | 2043 | \$ 4,141 | \$ 410.02 |
| Replacement | | | | 10 10013 | | 2053 | \$ 5,815 | \$ 575.78 |
| | | | | Lakes | | | | |
| | | | | 6 Years | | 2030 | \$ 30,439 | \$ 4,318.39 |
| | | | | o rouro | | 2000 | \$ 38,605 | \$ 5,476.94 |
| Lake Fountains | \$ 12,000 ea | 2 | \$ 24,000 | | 7 Years | 2044 | \$ 48,962 | \$ 6,946.31 |
| Replacement | | | | 7 Years | | 2051 | \$ 62,098 | \$ 8,809.88 |
| | | | | | | 2058 | \$ 78,757 | \$ 11,173.41 |
| | | | | | | | . , | |
| | 1 | 1 | l | Lighting | I | P | 1 | |
| Bollard Fixtures | \$ 500 ea | 15 | \$ 7,500 | 24 Years | 25 Years | 2048 | \$ 17,526 | \$ 683.73 |
| Replacement | + | | | 25 Years | | 2073 | \$ 40,956 | \$ 1,597.76 |
| Pole-Mounted | | | | 9 Years | | 2033 | \$ 8,763 | \$ 867.61 |
| Fixtures | \$ 480 ea | 13 | \$ 6,240 | 10 Years | 10 Years | 2043 | \$ 12,305 | \$ 1,218.35 |
| Replacement | | | | | | 2053 | \$ 17,280 | \$ 1,710.90 |
| | | | Mailbo | xes & Signag | e | | | |
| Mailboxes | | | | 24 Years | | 2048 | \$ 219,663 | \$ 8,569.41 |
| Replacement | \$ 2,000 ea | 47 | \$ 94,000 | 25 Years | 25 Years | 2073 | \$ 513,316 | \$ 20,025.30 |
| Signage Entry | | | | 9 Years | | 2033 | \$ 7,021 | \$ 695.20 |
| Monument | \$ 2,500 ea | 2 | \$ 5,000 | 0 10010 | 10 Years | 2043 | \$ 9,860 | \$ 976.25 |
| Refreshment Allowance | | | | 10 Years | | 2053 | \$ 13,846 | \$ 1,370.91 |

Avalon at Cypress Community Association, Inc. Reserve Study Expense Item Listing - Continued

| Reserve Items | Cost | | Estimated Remaining Life | Expected Life When New | Calendar Year | Estimated Future Cost | Raw Annual Payment | |
|------------------------------------|--------------|------|--------------------------------|---------------------------------|------------------|-----------------------------|--------------------------|-------------|
| | | | Painti | ng & Repairs | | | | |
| | | | | 7 Years | | 2031 | \$ 4,592 | \$ 569.50 |
| Painting Interior | | | | | | 2039 | \$ 6,025 | \$ 747.24 |
| Clubhouse | \$ 3,500 ea | 1 | \$ 3,500 | 8 Years | 8 Years | 2047 | \$ 7,906 | \$ 980.43 |
| | | | | | | 2055 | \$ 10,373 | \$ 1,286.4 |
| Painting Metal Unfunded | \$ 0.00 ea | 1 | \$0 | 35 Years | 35 Years | 2059 | \$ 0 | \$ 0.00 |
| | | | | 9 Years | | 2033 | \$ 2,809 | \$ 278.08 |
| Repairs Concrete & Pavers | \$ 2,000 ea | 1 | \$ 2,000 | 40.14 | 10 Years | 2043 | \$ 3,944 | \$ 390.50 |
| & Favels | | | | 10 Years | | 2053 | \$ 5,538 | \$ 548.37 |
| | | | | Pool | | | | |
| | | | | 7 Years | | 2031 | \$ 7,872 | \$ 976.29 |
| Chemical Controller Replacement | | | \$ 6,000 | 1 Touro | 8 Years | 2039 | \$ 10,329 | \$ 1,280.98 |
| | \$ 6,000 ea | 1 | | 8 Years | | 2000 | \$ 13,553 | \$ 1,680.75 |
| | | | | | | 2055 | \$ 17,783 | \$ 2,205.28 |
| | \$ 1,200 ea | | | 14 Years | | 2038 | \$ 3,994 | \$ 262.30 |
| Filters Replacement | | 2 | \$ 2,400 | 15 Years | 15 Years | 2053 | \$ 6,646 | \$ 436.50 |
| | | | | 3 Years | | 2027 | \$ 11,747 | \$ 2,925.19 |
| | | | | | | 2031 | \$ 13,455 | \$ 3,350.69 |
| | | | | | | 2035 | \$ 15,413 | \$ 3,838.09 |
| Kool-Deck | | | • • • • | | | 2039 | \$ 17,655 | \$ 4,396.39 |
| Recoating | \$ 1.75 ea | 5860 | \$ 10,255 | 4 Years | 4 Years | 2043 | \$ 20,223 | \$ 5,035.89 |
| | | | | | | 2047 | \$ 23,164 | \$ 5,768.42 |
| | | | | | | 2051 | \$ 26,534 | \$ 6,607.50 |
| | | | | | | 2055 | \$ 30,393 | \$ 7,568.64 |
| Kool-Deck | ¢ c E0 | E000 | ¢ 20 000 | 27 Years | 29. V | 2051 | \$ 98,554 | \$ 3,422.45 |
| Replacement | \$ 6.50 ea | 5860 | \$ 38,090 | 28 Years | 28 Years | 2079 | \$ 254,999 | \$ 8,855.25 |
| Pool Interior | ¢ 23 E09 oc | 1 | ¢ 22 E00 | 14 Years | 15 Vooro | 2038 | \$ 55,760 | \$ 3,662.19 |
| Refinishing | \$ 33,508 ea | 1 | \$ 33,508 | 15 Years | 15 Years | 2053 | \$ 92,790 | \$ 6,094.21 |
| | | | | 4 Years | | 2028 | \$ 2,844 | \$ 566.02 |
| Pumps & Motors | \$ 1 200 00 | 2 | \$ 2,400 | | 5 Years | 2033 | \$ 3,370 | \$ 670.74 |
| Replacement | \$ 1,200 ea | | | 5 Years | JIEdis | 2038 | \$ 3,994 | \$ 794.84 |
| | | | | | | 2043 | \$ 4,733 | \$ 941.9 |

Avalon at Cypress Community Association, Inc. Reserve Study Expense Item Listing - Continued

| Current Expected | | | | | | | | | | | | |
|----------------------------------|--|--|---|---|---|---|---|--|--|--|--|--|
| Reserve Items Unit Cost No Units | | Current Cost When New | Estimated Remaining Life | Expected Life When New | Calendar Year | Estimated Future Cost | Raw Annual Payment | | | | | |
| ¢ 1 000 | 0 | ¢ 0.400 | F \/ | F V | 2048 | \$ 5,608 | \$ 1,116.18 | | | | | |
| | | 5 Years | 5 Years | 2053 | \$ 6,646 | \$ 1,322.69 | | | | | | |
| | | | | | | | | | | | | |
| | | Ref | urbishment | | | | | | | | | |
| \$ 10 000 ea | 1 | \$ 10 000 | 24 Years | 25 Years | 2048 | \$ 23,368 | \$ 911.64 | | | | | |
| ψ 10,000 ea | I | φ 10,000 | 25 Years | 20 10013 | 2073 | \$ 54,608 | \$ 2,130.35 | | | | | |
| | | | | | | | | | | | | |
| Roofing | | | | | | | | | | | | |
| \$ 2,000 ea | 1 | \$ 2,000 | 29 Years | 30 Years | 2053 | \$ 5,538 | \$ 179.15 | | | | | |
| \$ 9.50 / ft ² | 4105 ft ² | \$ 38,998 | 29 Years | 30 Years | 2053 \$ 107,992 | | \$ 3,493.11 | | | | | |
| | | Sn | orto Courto | | | | | | | | | |
| | | ομι | | | 2022 | ¢ 10.000 | \$ 1,191.29 | | | | | |
| 0 0 75 / (12 | 44404 62 | \$ 8,568 | 9 Teals | 40.14 | | | | | | | | |
| \$ 0.75 / π ² | 11424 ft ² | | 10 Years | 10 Years | | | \$ 1,672.89 | | | | | |
| | | | | | 2053 | \$ 23,726 | \$ 2,349.20 | | | | | |
| | | | Tot Lot | | | | | | | | | |
| | | | | | | | | | | | | |
| \$ 0.00 ea | 1 | \$0 | 35 Years | 35 Years | 2059 | \$ 0 | \$ 0.00 | | | | | |
| \$ 25 000 ea | 1 | \$ 25 000 | 24 Years | 25 Vears | 2048 | \$ 58,421 | \$ 2,279.10 | | | | | |
| φ 20,000 ea | 25 Years | | 2010013 | 2073 | \$ 136,520 | \$ 5,325.88 | | | | | | |
| | | 24 Years | 25 Vooro | 2048 | \$ 46,737 | \$ 1,823.28 | | | | | | |
| \$ 20,000 ea | 1 | ֆ ∠∪,000 | 25 Years | 20 rears | 2073 | \$ 109,216 | \$ 4,260.70 | | | | | |
| ¢ 2 E00 | 4 | ¢ 0 500 | 24 Years | 05 V | 2048 | \$ 8,179 | \$ 319.07 | | | | | |
| φ 3,500 ea | | ა ა, ა იი | 25 Years | 20 rears | 2073 | \$ 19,113 | \$ 745.62 | | | | | |
| | \$ 1,200 ea \$ 10,000 ea \$ 2,000 ea \$ 9.50 / ft² \$ 0.75 / ft² | \u00em 2 \u00em 2 \u00em 1 \u00em 1 \u00em 1 \u00em 1 \u00em 1 \u00em 4105 ft² \u00em 11424 ft² \u00em 1 \u00em 1 \u00em 1 \u00em 1 \u00em 1 \u00em 1 \u00em 1 | Unit Cost No Units Cost When New \$1,200 ea 2 \$2,400 \$1,200 ea 1 \$10,000 \$10,000 ea 1 \$10,000 \$2,000 ea 1 \$10,000 \$2,000 ea 1 \$2,000 \$9.50 / ft ² 4105 ft ² \$38,998 \$0.75 / ft ² 11424 ft ² \$8,568 \$0.00 ea 1 \$0 \$25,000 ea 1 \$0 \$25,000 ea 1 \$20,000 \$20,000 ea 1 \$20,000 | Unit Cost No UnitsCost When NewEstimated Remaining Life\$ 1,200 ea2\$ 2,400\$ 7 ears\$ 1,200 ea2\$ 2,400\$ 7 ears\$ 10,000 ea1\$ 10,00024 Years 25 Years\$ 2,000 ea1\$ 2,00029 Years\$ 2,000 ea1\$ 2,00029 Years\$ 2,000 ea1\$ 38,99829 Years\$ 0.75 / ft²11424 ft²\$ 8,5689 Years\$ 0.75 / ft²11424 ft²\$ 8,5689 Years\$ 0.00 ea1\$ 035 Years\$ 0.00 ea1\$ 035 Years\$ 25,000 ea1\$ 20,00024 Years\$ 20,000 ea1\$ 20,00024 Years\$ 20,000 ea1\$ 20,00024 Years\$ 20,000 ea1\$ 20,00024 Years\$ 20,000 ea1\$ 20,00024 Years\$ 3,500 ea1\$ 3,50024 Years | Unit Cost No UnitsNo UnitsCost When NewEstimated Remaining LifeLife When New $\$$ 1,200 ea2 $\$$ 2,4005 Years5 Years $\$$ 1,200 ea2 $\$$ 2,4005 Years5 Years $\$$ 10,000 ea1 $\$$ 10,000 24 Years 25 Years25 Years $\$$ 10,000 ea1 $\$$ 2,00029 Years30 Years $\$$ 2,000 ea1 $\$$ 2,00029 Years30 Years $\$$ 2,000 ea1 $\$$ 2,00029 Years30 Years $\$$ 9,50 / ft²4105 ft² $\$$ 38,99829 Years30 Years $\$$ 9,50 / ft²11424 ft² $\$$ 8,5689 Years10 Years $\$$ 0,75 / ft²11424 ft² $\$$ 8,5689 Years10 Years $\$$ 0,75 / ft²11424 ft² $\$$ 8,56810 Years10 Years $\$$ 0,00 ea1 $\$$ 035 Years35 Years $\$$ 0,00 ea1 $\$$ 0 $$3$ Years $$2$ Years $\$$ 2,000 ea1 $\$$ 2,000 $$2$ Years $$2$ Years $\$$ 2,000 ea1 $\$$ 2,000 $$2$ Years $$2$ Years $\$$ 2,000 ea1 $\$$ 2,000 $$2$ Years $$2$ Years $\$$ 3,500 ea1 $\$$ 3,500 $$2$ Years $$2$ Years | Unit Cost Wein No UnitsCost When NewEstimated Remaining LifeLife When NewCalendar Year $\$ 1,200 ea$ $\$ 1,200 ea$ 2 $\$2,400$ 5 Years 5 Years 2048 2053 $\$ 10,000 ea$ 2 $\$10,000$ 24 Years 25 Years 2048 2073 $\$ 10,000 ea$ 1 $\$10,000$ 24 Years 25 Years 2048 2073 $\$ 10,000 ea$ 1 $\$2,000$ 24 Years | Unit CostNo UnitsCost When NewEstimated Remaining LifeLifeCalendar When NewEstimated Future Cost $3 1,200 ea$ 2 $2,2,000$ $3,2,000$ 5 Years 5 Years 2048 $20535,60820533 10,000 ea12,10,00024 Years25 Years204820735,23,60820733 10,000 ea12,100029 Years25 Years204820735,5,60820735,2,000 ea1$2,00029 Years30 Years2053$10,929$2,000 ea1$2,00029 Years30 Years2053$10,929$9,50/ ft^24105 ft²$38,99829 Years30 Years2053$10,929$0,075/ ft²11424 ft²$8,5689 Years10 Years2033$12,0322053$16,8962053$0,075/ ft²11424 ft²$8,5689 Years10 Years2033$12,0322053$16,8962053$0,075/ ft²11424 ft²$2,076$2,0243$2,0243$16,8962053$23,276$20,000 ea1$2,000$2,1968$2,59ea8$20,203$2,0248$58,212$2,0200$22,0000 ea1$20,000$2,0206$2,92068$2,02068$2,02068$3,3506$20,000 ea1$20,000$2,02068$2,02068$2,02068$2,02068$2,02068$2,02068$ | | | | | |

Avalon at Cypress Community Association, Inc. Reserve Study Expense Item Listing - Continued

Raw Annual Payments do not include earned interest, tax adjustments or payments made with inital reserves. Months Remaining in Calendar Year 2024: 12

Expected annual inflation: 3.40% Interest earned on reserve funds: 0.20% Initial Reserve: \$288,183

Avalon at Cypress Community Association, Inc. Funding Study Modified Cash Flow Analysis

| Calendar | | Annual | | Annual | Annual | Net | % | Fully |
|----------|--------------|-----------|---------|--------------|----------|------------|--------|------------|
| Year | Annual Dues | Interest | Salvage | Expenses | Income | Reserve | Funde | Funded |
| i cai | | 111101031 | | слрепзез | Tax | Funds | d | Balance |
| 2024 | \$ 24,813 | \$ 599 | | | \$ 180 | \$ 313,416 | 443.2% | \$ 70,709 |
| 2025 | \$ 24,813 | \$ 650 | | | \$ 195 | \$ 338,684 | 308.7% | \$ 109,727 |
| 2026 | \$ 24,813 | \$ 700 | | | \$ 210 | \$ 363,987 | 240.5% | \$ 151,355 |
| 2027 | \$ 24,813 | \$ 751 | | \$ 11,747 | \$ 225 | \$ 377,578 | 192.9% | \$ 195,728 |
| 2028 | \$ 24,813 | \$ 778 | | \$ 15,879 | \$ 233 | \$ 387,057 | 167.2% | \$ 231,440 |
| 2029 | \$ 24,813 | \$ 797 | | | \$ 239 | \$ 412,427 | 155.0% | \$ 266,077 |
| 2030 | \$ 24,813 | \$ 848 | | \$ 50,668 | \$ 254 | \$ 387,166 | 121.1% | \$ 319,825 |
| 2031 | \$ 24,813 | \$ 797 | | \$ 53,600 | \$ 239 | \$ 358,937 | 110.3% | \$ 325,487 |
| 2032 | \$ 24,813 | \$ 741 | | | \$ 222 | \$ 384,268 | 116.3% | \$ 330,513 |
| 2033 | \$ 24,813 | \$ 791 | | \$ 131,936 | \$ 237 | \$ 277,700 | 70.7% | \$ 392,863 |
| 2034 | \$ 76,750 | \$ 626 | | | \$ 188 | \$ 354,888 | 109.6% | \$ 323,698 |
| 2035 | \$ 76,750 | \$ 780 | | \$ 21,124 | \$ 234 | \$ 411,060 | 105.3% | \$ 390,492 |
| 2036 | \$ 76,750 | \$ 893 | | | \$ 268 | \$ 488,435 | 111.1% | \$ 439,698 |
| 2037 | \$ 76,750 | \$ 1,047 | | \$ 64,261 | \$ 314 | \$ 501,656 | 97.5% | \$ 514,446 |
| 2038 | \$ 76,750 | \$ 1,074 | | \$ 126,983 | \$ 322 | \$ 452,174 | 85.7% | \$ 527,351 |
| 2039 | \$ 76,750 | \$ 975 | | \$ 70,327 | \$ 292 | \$ 459,279 | 96.0% | \$ 478,393 |
| 2040 | \$ 76,750 | \$ 989 | | | \$ 297 | \$ 536,721 | 109.9% | \$ 488,573 |
| 2041 | \$ 76,750 | \$ 1,144 | | | \$ 343 | \$ 614,272 | 107.0% | \$ 574,156 |
| 2042 | \$ 76,750 | \$ 1,299 | | | \$ 390 | \$ 691,931 | 104.0% | \$ 665,066 |
| 2043 | \$ 102,181 | \$ 1,478 | | \$ 205,496 | \$ 443 | \$ 589,650 | 77.4% | \$ 761,571 |
| 2044 | \$ 102,181 | \$ 1,273 | | \$ 81,501 | \$ 382 | \$ 611,220 | 93.8% | \$ 651,356 |
| 2045 | \$ 102,181 | \$ 1,316 | | | \$ 395 | \$ 714,323 | 106.9% | \$ 668,238 |
| 2046 | \$ 102,181 | \$ 1,522 | | | \$ 457 | \$ 817,569 | 105.8% | \$ 772,738 |
| 2047 | \$ 102,181 | \$ 1,729 | | \$ 100,859 | \$ 519 | \$ 820,101 | 92.8% | \$ 883,658 |
| 2048 | \$ 102,181 | \$ 1,734 | | \$ 408,713 | \$ 520 | \$ 514,783 | 57.4% | \$ 896,976 |
| 2049 | \$ 102,181 | \$ 1,123 | | | \$ 337 | \$ 617,750 | 103.7% | \$ 595,879 |
| 2050 | \$ 102,181 | \$ 1,329 | | | \$ 399 | \$ 720,861 | 101.5% | \$ 710,344 |
| 2051 | \$ 102,181 | \$ 1,535 | | \$ 228,455 | \$ 461 | \$ 595,662 | 71.6% | \$ 832,006 |
| 2052 | \$ 102,181 | \$ 1,285 | | | \$ 386 | \$ 698,742 | 96.4% | \$ 725,004 |
| 2053 | \$ 102,181 | \$ 1,491 | | \$ 642,533 | \$ 447 | \$ 159,434 | 18.7% | \$ 854,126 |
| 2054 | \$ 102,181 | \$ 413 | | | \$ 124 | \$ 261,904 | 94.6% | \$ 276,863 |
| Totals : | \$ 2,165,048 | \$ 32,506 | \$0 | \$ 2,214,082 | \$ 9,752 | · · · | | · · · |

The cash distribution shown in this table applies to repair and replacement cash reserves only.

Basis of Funding Study - Modified Cash Flow

Cash reserves have been set to a minimum of 0.0% of Fully Funded reserves.


Cash Flow has been modified with the forced Fixed Payments.

Months Remaining in Calendar Year 2024: 12 Inflation = 3.40 % Interest = 0.20 %

Study Life = 30 years Initial Reserve Funds = \$288,183.41 Final Reserve Value = \$261,903.67

Annual Payments Held Constant for 9 years

Prepared by Great Boards, LLC



Avalon at Cypress Community Association, Inc. Funding Study Cash Flow by Calendar Year - Continued

Calendar Years

Avalon at Cypress Community Association, Inc. Modified Reserve Dues Summary

Projected Dues by Month and by Calendar Year

| Calendar Year | Member Monthly Operations Payment | Member Monthly Reserve Payment | Member Total Monthly Payment | Member Total Annual Payment | Monthly Reserve Payment | Annual Reserve Payment |
|------------------|---|-----------------------------------|---------------------------------|--------------------------------|----------------------------|---------------------------|
| 2024 | NA | \$ 1.48 | \$ 1.48 | \$ 17.75 | \$ 2,068 | \$ 24,813 |
| 2025 | NA | \$ 1.48 | \$ 1.48 | \$ 17.75 | \$ 2,068 | \$ 24,813 |
| 2026 | NA | \$ 1.48 | \$ 1.48 | \$ 17.75 | \$ 2,068 | \$ 24,813 |
| 2027 | NA | \$ 1.48 | \$ 1.48 | \$ 17.75 | \$ 2,068 | \$ 24,813 |
| 2028 | NA | \$ 1.48 | \$ 1.48 | \$ 17.75 | \$ 2,068 | \$ 24,813 |
| 2029 | NA | \$ 1.48 | \$ 1.48 | \$ 17.75 | \$ 2,068 | \$ 24,813 |
| 2030 | NA | \$ 1.48 | \$ 1.48 | \$ 17.75 | \$ 2,068 | \$ 24,813 |
| 2031 | NA | \$ 1.48 | \$ 1.48 | \$ 17.75 | \$ 2,068 | \$ 24,813 |
| 2032 | NA | \$ 1.48 | \$ 1.48 | \$ 17.75 | \$ 2,068 | \$ 24,813 |
| 2033 | NA | \$ 1.48 | \$ 1.48 | \$ 17.75 | \$ 2,068 | \$ 24,813 |
| 2034 | NA | \$ 4.57 | \$ 4.57 | \$ 54.90 | \$ 6,396 | \$ 76,750 |
| 2035 | NA | \$ 4.57 | \$ 4.57 | \$ 54.90 | \$ 6,396 | \$ 76,750 |
| 2036 | NA | \$ 4.57 | \$ 4.57 | \$ 54.90 | \$ 6,396 | \$ 76,750 |
| 2037 | NA | \$ 4.57 | \$ 4.57 | \$ 54.90 | \$ 6,396 | \$ 76,750 |
| 2038 | NA | \$ 4.57 | \$ 4.57 | \$ 54.90 | \$ 6,396 | \$ 76,750 |
| 2039 | NA | \$ 4.57 | \$ 4.57 | \$ 54.90 | \$ 6,396 | \$ 76,750 |
| 2040 | NA | \$ 4.57 | \$ 4.57 | \$ 54.90 | \$ 6,396 | \$ 76,750 |
| 2041 | NA | \$ 4.57 | \$ 4.57 | \$ 54.90 | \$ 6,396 | \$ 76,750 |
| 2042 | NA | \$ 4.57 | \$ 4.57 | \$ 54.90 | \$ 6,396 | \$ 76,750 |
| 2043 | NA | \$ 6.09 | \$ 6.09 | \$ 73.09 | \$ 8,515 | \$ 102,181 |
| 2044 | NA | \$ 6.09 | \$ 6.09 | \$ 73.09 | \$ 8,515 | \$ 102,181 |
| 2045 | NA | \$ 6.09 | \$ 6.09 | \$ 73.09 | \$ 8,515 | \$ 102,181 |
| 2046 | NA | \$ 6.09 | \$ 6.09 | \$ 73.09 | \$ 8,515 | \$ 102,181 |
| 2047 | NA | \$ 6.09 | \$ 6.09 | \$ 73.09 | \$ 8,515 | \$ 102,181 |
| 2048 | NA | \$ 6.09 | \$ 6.09 | \$ 73.09 | \$ 8,515 | \$ 102,181 |
| 2049 | NA | \$ 6.09 | \$ 6.09 | \$ 73.09 | \$ 8,515 | \$ 102,181 |
| 2050 | NA | \$ 6.09 | \$ 6.09 | \$ 73.09 | \$ 8,515 | \$ 102,181 |
| 2051 | NA | \$ 6.09 | \$ 6.09 | \$ 73.09 | \$ 8,515 | \$ 102,181 |
| 2052 | NA | \$ 6.09 | \$ 6.09 | \$ 73.09 | \$ 8,515 | \$ 102,181 |
| 2053 | NA | \$ 6.09 | \$ 6.09 | \$ 73.09 | \$ 8,515 | \$ 102,181 |
| 2054 | NA | \$ 6.09 | \$ 6.09 | \$ 73.09 | \$ 8,515 | \$ 102,181 |

Dues Summary has been modified with forced Fixed Payments.

In the context of the Reserve Payment Summary, the "Annual Reserve Payment" corresponds with the "Annual

Revenue" in the Cash Flow report.

Number of Payment Months in Calendar Year 2024: 12

Number of Years of Constant Payments: 9

Avalon at Cypress Community Association, Inc. Funding Study Payment Summary by Calendar Year - Continued No of Dues Paying Members: 1398

| Item Name | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 |
|---|----------|----------|----------|----------|----------|--------------|---------------|---------------|----------|----------|----------|----------|----------|----------|----------|----------|
| | | | | | F | Reserve Cate | gory : Appli | ances & Ele | ctronics | | | | | | | |
| Appliances Ice-maker Replacement | \$ 123 | \$ 123 | \$ 123 | \$ 123 | \$ 122 | \$ 121 | \$ 121 | \$ 118 | \$ 114 | \$ 114 | \$ 327 | \$ 327 | \$ 323 | \$ 323 | \$ 313 | \$ 485 |
| Appliances Refrigerator- freezer Replacement | \$ 185 | \$ 185 | \$ 185 | \$ 185 | \$ 183 | \$ 182 | \$ 182 | \$ 176 | \$ 171 | \$ 171 | \$ 490 | \$ 490 | \$ 485 | \$ 485 | \$ 469 | \$ 728 |
| Electronics Access Control System Allowance | \$ 474 | \$ 474 | \$ 474 | \$ 474 | \$ 471 | \$ 553 | \$ 553 | \$ 536 | \$ 520 | \$ 520 | \$ 1,768 | \$ 1,768 | \$ 1,749 | \$ 1,749 | \$ 1,692 | \$ 1,870 |
| Electronics Fire Control Panel Replacement | \$ 90 | \$ 90 | \$ 90 | \$ 90 | \$ 89 | \$ 88 | \$ 88 | \$ 86 | \$ 83 | \$ 83 | \$ 238 | \$ 238 | \$ 354 | \$ 354 | \$ 342 | \$ 319 |
| Electronics Observation Cameras Allowance | \$ 95 | \$ 95 | \$ 95 | \$ 95 | \$ 94 | \$ 110 | \$ 110 | \$ 107 | \$ 104 | \$ 104 | \$ 353 | \$ 353 | \$ 350 | \$ 350 | \$ 338 | \$ 374 |
| Electronics Televisions Replacement | \$ 129 | \$ 129 | \$ 129 | \$ 129 | \$ 128 | \$ 127 | \$ 127 | \$ 123 | \$ 119 | \$ 119 | \$ 479 | \$ 479 | \$ 474 | \$ 474 | \$ 459 | \$ 428 |
| Appliances & Electronics Subtotal : | \$ 1,096 | \$ 1,096 | \$ 1,096 | \$ 1,096 | \$ 1,087 | \$ 1,181 | \$ 1,181 | \$ 1,146 | \$ 1,111 | \$ 1,111 | \$ 3,655 | \$ 3,655 | \$ 3,735 | \$ 3,735 | \$ 3,613 | \$ 4,204 |
| | | | | | | Reserve Ca | ategory : Dra | ainage & Irri | gation | | | | | | | |
| Drainage Stormwater Management Allowance | \$ 879 | \$ 879 | \$ 879 | \$ 879 | \$ 873 | \$ 865 | \$ 865 | \$ 839 | \$ 814 | \$ 814 | \$ 2,334 | \$ 2,334 | \$ 2,309 | \$ 2,309 | \$ 2,233 | \$ 3,467 |
| Irrigation Backflow Preventers Replacement | \$ 246 | \$ 246 | \$ 246 | \$ 246 | \$ 245 | \$ 242 | \$ 242 | \$ 235 | \$ 228 | \$ 228 | \$ 917 | \$ 917 | \$ 907 | \$ 907 | \$ 878 | \$ 819 |
| Irrigation Controllers Allowance | \$ 100 | \$ 100 | \$ 100 | \$ 100 | \$ 99 | \$ 98 | \$ 98 | \$ 95 | \$ 92 | \$ 92 | \$ 265 | \$ 265 | \$ 393 | \$ 393 | \$ 380 | \$ 355 |
| Drainage & Irrigation Subtotal : | \$ 1,225 | \$ 1,225 | \$ 1,225 | \$ 1,225 | \$ 1,217 | \$ 1,205 | \$ 1,205 | \$ 1,169 | \$ 1,134 | \$ 1,134 | \$ 3,516 | \$ 3,516 | \$ 3,609 | \$ 3,609 | \$ 3,491 | \$ 4,641 |
| | | | | | | Reserve | Category : | Fences & W | alis | | | | | | | |
| Fences Chain-link Replacement | \$ 534 | \$ 534 | \$ 534 | \$ 534 | \$ 530 | \$ 525 | \$ 525 | \$ 510 | \$ 494 | \$ 494 | \$ 1,417 | \$ 1,417 | \$ 1,401 | \$ 1,401 | \$ 1,356 | \$ 1,265 |
| Fences Metal Replacement | \$ 697 | \$ 697 | \$ 697 | \$ 697 | \$ 692 | \$ 686 | \$ 686 | \$ 665 | \$ 645 | \$ 645 | \$ 1,850 | \$ 1,850 | \$ 1,830 | \$ 1,830 | \$ 1,771 | \$ 1,652 |

| 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 |
|----------|--|---|---|---|---|---|--|---|---|--|---|--|--|---|--|
| \$ 168 | \$ 168 | \$ 168 | \$ 168 | \$ 167 | \$ 165 | \$ 165 | \$ 160 | \$ 155 | \$ 155 | \$ 626 | \$ 626 | \$619 | \$ 619 | \$ 599 | \$ 559 |
| \$ 1,399 | \$ 1,399 | \$ 1,399 | \$ 1,399 | \$ 1,389 | \$ 1,376 | \$ 1,376 | \$ 1,335 | \$ 1,294 | \$ 1,294 | \$ 3,893 | \$ 3,893 | \$ 3,850 | \$ 3,850 | \$ 3,726 | \$ 3,476 |
| | | | | | Rese | rve Categor | y : Furniture |) | | | | | | | |
| \$ 333 | \$ 333 | \$ 333 | \$ 333 | \$ 330 | \$ 327 | \$ 327 | \$ 318 | \$ 308 | \$ 308 | \$ 1,240 | \$ 1,240 | \$ 1,226 | \$ 1,226 | \$ 1,186 | \$ 1,107 |
| \$ 69 | \$ 69 | \$ 69 | \$ 69 | \$ 68 | \$ 68 | \$ 68 | \$ 83 | \$ 81 | \$ 81 | \$ 232 | \$ 232 | \$ 229 | \$ 229 | \$ 281 | \$ 262 |
| \$ 1,119 | \$ 1,119 | \$ 1,119 | \$ 1,119 | \$ 1,111 | \$ 1,101 | \$ 1,101 | \$ 1,068 | \$ 1,035 | \$ 1,035 | \$ 4,170 | \$ 4,170 | \$ 4,124 | \$ 4,124 | \$ 3,990 | \$ 3,723 |
| \$ 1,086 | \$ 1,086 | \$ 1,086 | \$ 1,086 | \$ 1,078 | \$ 1,068 | \$ 1,068 | \$ 1,314 | \$ 1,274 | \$ 1,274 | \$ 3,655 | \$ 3,655 | \$ 3,615 | \$ 3,615 | \$ 4,435 | \$ 4,139 |
| \$ 1,381 | \$ 1,381 | \$ 1,381 | \$ 1,381 | \$ 1,372 | \$ 1,359 | \$ 1,359 | \$ 1,318 | \$ 1,677 | \$ 1,677 | \$ 4,809 | \$ 4,809 | \$ 4,757 | \$ 4,757 | \$ 4,602 | \$ 4,294 |
| \$ 3,988 | \$ 3,988 | \$ 3,988 | \$ 3,988 | \$ 3,959 | \$ 3,923 | \$ 3,923 | \$ 4,101 | \$ 4,375 | \$ 4,375 | \$ 14,106 | \$ 14,106 | \$ 13,951 | \$ 13,951 | \$ 14,494 | \$ 13,525 |
| | | | | | Reserve (| Category : H | VAC & Plum | bing | | | | | | | |
| \$ 1,175 | \$ 1,175 | \$ 1,175 | \$ 1,175 | \$ 1,167 | \$ 1,156 | \$ 1,156 | \$ 1,121 | \$ 1,087 | \$ 1,087 | \$ 4,378 | \$ 4,378 | \$ 4,330 | \$ 4,330 | \$ 4,189 | \$ 3,909 |
| \$ 55 | \$ 55 | \$ 55 | \$ 55 | \$ 55 | \$ 54 | \$ 54 | \$ 53 | \$ 51 | \$ 51 | \$ 146 | \$ 146 | \$ 145 | \$ 145 | \$ 140 | \$ 131 |
| \$ 474 | \$ 474 | \$ 474 | \$ 474 | \$ 471 | \$ 553 | \$ 553 | \$ 536 | \$ 520 | \$ 520 | \$ 1,768 | \$ 1,768 | \$ 1,749 | \$ 1,749 | \$ 1,692 | \$ 1,870 |
| \$ 117 | \$ 117 | \$ 117 | \$ 117 | \$ 117 | \$ 116 | \$ 116 | \$ 112 | \$ 109 | \$ 109 | \$ 438 | \$ 438 | \$ 433 | \$ 433 | \$ 419 | \$ 391 |
| \$ 1,821 | \$ 1,821 | \$ 1,821 | \$ 1,821 | \$ 1,810 | \$ 1,879 | \$ 1,879 | \$ 1,822 | \$ 1,767 | \$ 1,767 | \$ 6,730 | \$ 6,730 | \$ 6,657 | \$ 6,657 | \$ 6,440 | \$ 6,301 |
| | | | | 1 | Ros | erve Caterr | nrv · lakes | | | | | | | | |
| \$ 1,737 | \$ 1,737 | \$ 1,737 | \$ 1,737 | \$ 1,725 | \$ 1,709 | \$ 1,709 | \$ 2,103 | \$ 2,039 | \$ 2,039 | \$ 5,848 | \$ 5,848 | \$ 5,784 | \$ 5,784 | \$ 7,097 | \$ 6,622 |
| | \$ 168 \$ 1,399 \$ 333 \$ 69 \$ 1,119 \$ 1,086 \$ 1,381 \$ 3,988 \$ 1,381 \$ 3,988 \$ 1,175 \$ 55 \$ 474 \$ 117 \$ 1,821 \$ 1,821 | \$ 168 \$ 168 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 333 \$ 333 \$ 69 \$ 69 \$ 1,119 \$ 1,119 \$ 1,086 \$ 1,086 \$ 1,381 \$ 1,381 \$ 3,988 \$ 3,988 \$ 1,175 \$ 1,175 \$ 555 \$ 555 \$ 474 \$ 474 \$ 1,821 \$ 1,821 | \$ 168 \$ 168 \$ 168 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 333 \$ 333 \$ 333 \$ 69 \$ 69 \$ 69 \$ 1,119 \$ 1,119 \$ 1,119 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,381 \$ 1,381 \$ 1,381 \$ 3,988 \$ 3,988 \$ 3,988 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,17 \$ 1,177 \$ 117 \$ 1,821 \$ 1,821 \$ 1,821 \$ 1,821 \$ 1,821 \$ 1,821 | \$ 168 \$ 168 \$ 168 \$ 168 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 333 \$ 333 \$ 333 \$ 333 \$ 69 \$ 69 \$ 69 \$ 69 \$ 1,119 \$ 1,119 \$ 1,119 \$ 1,119 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,381 \$ 1,381 \$ 1,381 \$ 1,381 \$ 3,988 \$ 3,988 \$ 3,988 \$ 3,988 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,17 \$ 1,175 \$ 1,175 \$ 1,17 \$ 1,175 \$ 1,175 \$ 1,17 \$ 1,175 \$ 1,175 \$ 1,17 \$ 1,175 \$ 1,175 | \$ 168 \$ 168 \$ 168 \$ 168 \$ 168 \$ 167 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,389 \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 69 \$ 69 \$ 69 \$ 69 \$ 68 \$ 1,119 \$ 1,119 \$ 1,119 \$ 1,119 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,381 \$ 1,381 \$ 1,381 \$ 1,372 \$ 3,988 \$ 3,988 \$ 3,988 \$ 3,988 \$ 3,959 \$ 1,381 \$ 1,381 \$ 1,381 \$ 1,372 \$ 1,381 \$ 1,381 \$ 1,381 \$ 1,372 \$ 3,988 \$ 3,988 \$ 3,988 \$ 3,988 \$ 3,959 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,167 \$ 555 \$ 555 \$ 555 \$ 555 \$ 474 \$ 474 \$ 474 \$ 471 \$ 1,821 \$ 1,821 \$ 1,821 \$ 1,810 \$ 1,821 \$ 1,821 | \$ 168 \$ 168 \$ 168 \$ 168 \$ 168 \$ 167 \$ 165 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,389 \$ 1,376 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,389 \$ 1,376 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,389 \$ 1,376 \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 330 \$ 327 \$ 69 \$ 69 \$ 69 \$ 69 \$ 69 \$ 68 \$ 68 \$ 1,119 \$ 1,119 \$ 1,119 \$ 1,119 \$ 1,111 \$ 1,101 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,381 \$ 1,381 \$ 1,381 \$ 1,381 \$ 1,372 \$ 1,359 \$ 3,988 \$ 3,988 \$ 3,988 \$ 3,988 \$ 3,959 \$ 3,923 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,175 \$ 1,167 \$ 1,156 \$ 555 \$ 555 \$ 555 \$ 555 \$ 553 \$ 553 <t< td=""><td>\$ 168 \$ 168 \$ 168 \$ 168 \$ 167 \$ 165 \$ 165 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,389 \$ 1,376 \$ 1,376 \$ 333 \$ 335 \$ 31,011 \$ 1</td><td>\$ 168 \$ 168 \$ 168 \$ 168 \$ 167 \$ 165 \$ 165 \$ 160 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,376 \$ 1,376 \$ 1,335 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,376 \$ 1,376 \$ 1,335 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,376 \$ 1,376 \$ 1,335 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,380 \$ 1,376 \$ 1,335 \$ 333 \$ 337 \$ 327 \$ 318 \$ 1,119 \$ 1,119 \$ 1,119 \$ 1,119 \$ 1,175 \$ 1,376</td><td>§ 168 § 168 § 168 § 168 § 167 § 165 § 165 § 160 § 155 § 1,399 § 1,399 § 1,399 § 1,399 § 1,399 § 1,399 § 1,376 § 160 § 155 § 1,399 § 1,399 § 1,399 § 1,399 § 1,399 § 1,376 § 160 § 155 § 1,399 § 1,399 § 1,399 § 1,399 § 1,399 § 1,376 § 1,376 § 1,376 § 1,376 § 1,376 § 1,376 § 1,375 § 1,294 VEVEVEXENT § 333 § 333 § 333 § 333 § 330 § 327 § 327 § 318 § 308 § 69 § 69 § 69 § 69 § 68 § 68 § 48 § 108 § 1,035 § 1,119 § 1,119 § 1,119 § 1,111 § 1,101 § 1,068 § 1,035 § 1,035 § 1,314 § 1,274 § 1,381 § 1,381 § 1,381 § 1,371 § 1,375 § 1,359 § 1,359 § 1,318 § 1,677</td><td>\$ 168 \$ 168 \$ 168 \$ 168 \$ 167 \$ 165 \$ 165 \$ 160 \$ 155 \$ 155 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,376 \$ 1,376 \$ 1,335 \$ 1,294 \$ 1,294 Reserve Category: Furniture \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 330 \$ 327 \$ 318 \$ 308 \$ 308 \$ 69 \$ 69 \$ 69 \$ 69 \$ 69 \$ 69 \$ 68 \$ 68 \$ 83 \$ 81 \$ 1,119 \$ 1,119 \$ 1,119 \$ 1,119 \$ 1,101 \$ 1,006 \$ 1,035 \$ 1,035 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,037 \$ 1,371 \$ 1,381 \$ 1,381 \$ 1,381 \$ 1,381 \$ 1,381 \$ 1,381 \$ 1,372 \$ 1,359 \$ 1,318 \$ 1,677 \$ 1,677 \$ 3,988 \$ 3,988 \$ 3,988 \$ 3,988 \$ 3,983 \$ 3,923 \$ 3,323<td>\$ 168 \$ 168 \$ 168 \$ 168 \$ 169 \$ 165 \$ 165 \$ 165 \$ 160 \$ 155 \$ 155 \$ 626 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,376 \$ 1,376 \$ 1,335 \$ 1,294 \$ 3,893 Reserve Category: Furniture \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 330 \$ 327 \$ 318 \$ 308 \$ 308 \$ 1,244 \$ 69 \$ 69 \$ 69 \$ 69 \$ 69 \$ 69 \$ 69 \$ 69 \$ 69 \$ 1,119 \$ 1,111 \$ 1,101 \$ 1,006 \$ 1,035 \$ 1,075 \$ 1,175 \$ 1,381</td><td>\$ 168 \$ 168 \$ 168 \$ 168 \$ 168 \$ 167 \$ 165 \$ 165 \$ 160 \$ 155 \$ 155 \$ 626 \$ 626 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,376 \$ 1,376 \$ 1,376 \$ 1,375 \$ 1,376 \$ 1,376 \$ 1,375 \$ 1,294 \$ 1,294 \$ 3,893 \$ 3,893 VENEWE Category : Furniture \$ 333 \$ 3327 \$ 318 \$ 318 \$ 318 \$ 318 \$ 318 \$ 3185 \$ 3105 \$ 1,170 \$ 1,170 \$ 1,170 \$ 1</td><td>\$ 168 \$ 168 \$ 168 \$ 168 \$ 168 \$ 167 \$ 165 \$ 165 \$ 150 \$ 155 \$ 626 \$ 626 \$ 619 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,389 \$ 1,370 \$ 1,375 \$ 1,335 \$ 1,244 \$ 1,244 \$ 3,893 \$ 3,850 VENUE VENUE \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 337 \$ 327 \$ 318 \$ 308 \$ 308 \$ 1,240 \$ 1,241</td></td></t<> <td>\$ 168 \$ 168 \$ 168 \$ 168 \$ 168 \$ 167 \$ 165 \$ 165 \$ 155 \$ 155 \$ 626 \$ 626 \$ 619 \$ 519 \$ 1,399 \$ 1,390 \$ 1,390 \$ 1,390 \$ 1,390 \$ 1,390 \$ 1,390 \$ 1,390 \$ 1,390 \$ 1,390 \$ 1,390 \$ 1,390 \$ 1,390 \$ 3,390 \$ 3,390 \$ 1,370 \$ 1,370 \$ 1,291 \$ 1,240 \$ 1,240 \$ 1,226 \$ 1,226 \$ 699 \$ 699 \$ 699 \$ 699 \$ 699 \$ 699 \$ 699 \$ 699 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,035 \$ 1,035 \$ 1,035 \$ 4,170 \$ 4,170 \$ 4,124 \$ 4,124 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$</td> <td>\$ 168 \$ 168 \$ 168 \$ 168 \$ 167 \$ 105 \$ 165 \$ 100 \$ 155 \$ 155 \$ 626 \$ 628 \$ 619 \$ 619 \$ 519 \$ 1.399 \$ 1.399 \$ 1.399 \$ 1.399 \$ 1.399 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.290 \$ 1.290 \$ 3.893 \$ 3.890 \$</td> | \$ 168 \$ 168 \$ 168 \$ 168 \$ 167 \$ 165 \$ 165 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,389 \$ 1,376 \$ 1,376 \$ 333 \$ 335 \$ 31,011 \$ 1 | \$ 168 \$ 168 \$ 168 \$ 168 \$ 167 \$ 165 \$ 165 \$ 160 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,376 \$ 1,376 \$ 1,335 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,376 \$ 1,376 \$ 1,335 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,376 \$ 1,376 \$ 1,335 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,380 \$ 1,376 \$ 1,335 \$ 333 \$ 337 \$ 327 \$ 318 \$ 1,119 \$ 1,119 \$ 1,119 \$ 1,119 \$ 1,175 \$ 1,376 | § 168 § 168 § 168 § 168 § 167 § 165 § 165 § 160 § 155 § 1,399 § 1,399 § 1,399 § 1,399 § 1,399 § 1,399 § 1,376 § 160 § 155 § 1,399 § 1,399 § 1,399 § 1,399 § 1,399 § 1,376 § 160 § 155 § 1,399 § 1,399 § 1,399 § 1,399 § 1,399 § 1,376 § 1,376 § 1,376 § 1,376 § 1,376 § 1,376 § 1,375 § 1,294 VEVEVEXENT § 333 § 333 § 333 § 333 § 330 § 327 § 327 § 318 § 308 § 69 § 69 § 69 § 69 § 68 § 68 § 48 § 108 § 1,035 § 1,119 § 1,119 § 1,119 § 1,111 § 1,101 § 1,068 § 1,035 § 1,035 § 1,314 § 1,274 § 1,381 § 1,381 § 1,381 § 1,371 § 1,375 § 1,359 § 1,359 § 1,318 § 1,677 | \$ 168 \$ 168 \$ 168 \$ 168 \$ 167 \$ 165 \$ 165 \$ 160 \$ 155 \$ 155 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,376 \$ 1,376 \$ 1,335 \$ 1,294 \$ 1,294 Reserve Category: Furniture \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 330 \$ 327 \$ 318 \$ 308 \$ 308 \$ 69 \$ 69 \$ 69 \$ 69 \$ 69 \$ 69 \$ 68 \$ 68 \$ 83 \$ 81 \$ 1,119 \$ 1,119 \$ 1,119 \$ 1,119 \$ 1,101 \$ 1,006 \$ 1,035 \$ 1,035 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,037 \$ 1,371 \$ 1,381 \$ 1,381 \$ 1,381 \$ 1,381 \$ 1,381 \$ 1,381 \$ 1,372 \$ 1,359 \$ 1,318 \$ 1,677 \$ 1,677 \$ 3,988 \$ 3,988 \$ 3,988 \$ 3,988 \$ 3,983 \$ 3,923 \$ 3,323 <td>\$ 168 \$ 168 \$ 168 \$ 168 \$ 169 \$ 165 \$ 165 \$ 165 \$ 160 \$ 155 \$ 155 \$ 626 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,376 \$ 1,376 \$ 1,335 \$ 1,294 \$ 3,893 Reserve Category: Furniture \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 330 \$ 327 \$ 318 \$ 308 \$ 308 \$ 1,244 \$ 69 \$ 69 \$ 69 \$ 69 \$ 69 \$ 69 \$ 69 \$ 69 \$ 69 \$ 1,119 \$ 1,111 \$ 1,101 \$ 1,006 \$ 1,035 \$ 1,075 \$ 1,175 \$ 1,381</td> <td>\$ 168 \$ 168 \$ 168 \$ 168 \$ 168 \$ 167 \$ 165 \$ 165 \$ 160 \$ 155 \$ 155 \$ 626 \$ 626 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,376 \$ 1,376 \$ 1,376 \$ 1,375 \$ 1,376 \$ 1,376 \$ 1,375 \$ 1,294 \$ 1,294 \$ 3,893 \$ 3,893 VENEWE Category : Furniture \$ 333 \$ 3327 \$ 318 \$ 318 \$ 318 \$ 318 \$ 318 \$ 3185 \$ 3105 \$ 1,170 \$ 1,170 \$ 1,170 \$ 1</td> <td>\$ 168 \$ 168 \$ 168 \$ 168 \$ 168 \$ 167 \$ 165 \$ 165 \$ 150 \$ 155 \$ 626 \$ 626 \$ 619 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,389 \$ 1,370 \$ 1,375 \$ 1,335 \$ 1,244 \$ 1,244 \$ 3,893 \$ 3,850 VENUE VENUE \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 337 \$ 327 \$ 318 \$ 308 \$ 308 \$ 1,240 \$ 1,241</td> | \$ 168 \$ 168 \$ 168 \$ 168 \$ 169 \$ 165 \$ 165 \$ 165 \$ 160 \$ 155 \$ 155 \$ 626 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,376 \$ 1,376 \$ 1,335 \$ 1,294 \$ 3,893 Reserve Category: Furniture \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 330 \$ 327 \$ 318 \$ 308 \$ 308 \$ 1,244 \$ 69 \$ 69 \$ 69 \$ 69 \$ 69 \$ 69 \$ 69 \$ 69 \$ 69 \$ 1,119 \$ 1,111 \$ 1,101 \$ 1,006 \$ 1,035 \$ 1,075 \$ 1,175 \$ 1,381 | \$ 168 \$ 168 \$ 168 \$ 168 \$ 168 \$ 167 \$ 165 \$ 165 \$ 160 \$ 155 \$ 155 \$ 626 \$ 626 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,376 \$ 1,376 \$ 1,376 \$ 1,375 \$ 1,376 \$ 1,376 \$ 1,375 \$ 1,294 \$ 1,294 \$ 3,893 \$ 3,893 VENEWE Category : Furniture \$ 333 \$ 3327 \$ 318 \$ 318 \$ 318 \$ 318 \$ 318 \$ 3185 \$ 3105 \$ 1,170 \$ 1,170 \$ 1,170 \$ 1 | \$ 168 \$ 168 \$ 168 \$ 168 \$ 168 \$ 167 \$ 165 \$ 165 \$ 150 \$ 155 \$ 626 \$ 626 \$ 619 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,389 \$ 1,370 \$ 1,375 \$ 1,335 \$ 1,244 \$ 1,244 \$ 3,893 \$ 3,850 VENUE VENUE \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 333 \$ 337 \$ 327 \$ 318 \$ 308 \$ 308 \$ 1,240 \$ 1,241 | \$ 168 \$ 168 \$ 168 \$ 168 \$ 168 \$ 167 \$ 165 \$ 165 \$ 155 \$ 155 \$ 626 \$ 626 \$ 619 \$ 519 \$ 1,399 \$ 1,390 \$ 1,390 \$ 1,390 \$ 1,390 \$ 1,390 \$ 1,390 \$ 1,390 \$ 1,390 \$ 1,390 \$ 1,390 \$ 1,390 \$ 1,390 \$ 3,390 \$ 3,390 \$ 1,370 \$ 1,370 \$ 1,291 \$ 1,240 \$ 1,240 \$ 1,226 \$ 1,226 \$ 699 \$ 699 \$ 699 \$ 699 \$ 699 \$ 699 \$ 699 \$ 699 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,035 \$ 1,035 \$ 1,035 \$ 4,170 \$ 4,170 \$ 4,124 \$ 4,124 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ 1,086 \$ | \$ 168 \$ 168 \$ 168 \$ 168 \$ 167 \$ 105 \$ 165 \$ 100 \$ 155 \$ 155 \$ 626 \$ 628 \$ 619 \$ 619 \$ 519 \$ 1.399 \$ 1.399 \$ 1.399 \$ 1.399 \$ 1.399 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.390 \$ 1.290 \$ 1.290 \$ 3.893 \$ 3.890 \$ |

| | | Avaiuit | al Cypres | s commu | mily Asso | | nc. Fundi | iy Aujusi | eu neven | ue by Ca | enual ie | | lueu | | | |
|---|----------|----------|-----------|----------|-----------|------------|---------------|--------------|----------|----------|-----------|-----------|-----------|-----------|----------|----------|
| Item Name | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 |
| Bollard Fixtures Replacement | \$ 275 | \$ 275 | \$ 275 | \$ 275 | \$ 273 | \$ 271 | \$ 271 | \$ 263 | \$ 255 | \$ 255 | \$ 730 | \$ 730 | \$ 722 | \$ 722 | \$ 699 | \$ 652 |
| Pole-Mounted Fixtures Replacement | \$ 349 | \$ 349 | \$ 349 | \$ 349 | \$ 347 | \$ 344 | \$ 344 | \$ 333 | \$ 323 | \$ 323 | \$ 1,301 | \$ 1,301 | \$ 1,286 | \$ 1,286 | \$ 1,244 | \$ 1,161 |
| Lighting Subtotal : | \$ 624 | \$ 624 | \$ 624 | \$ 624 | \$ 620 | \$ 615 | \$ 615 | \$ 596 | \$ 578 | \$ 578 | \$ 2,031 | \$ 2,031 | \$ 2,008 | \$ 2,008 | \$ 1,943 | \$ 1,813 |
| | | | | | | Reserve Ca | ategory : Ma | ilboxes & Si | gnage | | | | | | | |
| Mailboxes Replacement | \$ 3,447 | \$ 3,447 | \$ 3,447 | \$ 3,447 | \$ 3,424 | \$ 3,392 | \$ 3,392 | \$ 3,291 | \$ 3,190 | \$ 3,190 | \$ 9,150 | \$ 9,150 | \$ 9,050 | \$ 9,050 | \$ 8,755 | \$ 8,169 |
| Signage Entry Monument Refreshment Allowance | \$ 280 | \$ 280 | \$ 280 | \$ 280 | \$ 278 | \$ 275 | \$ 275 | \$ 267 | \$ 259 | \$ 259 | \$ 1,042 | \$ 1,042 | \$ 1,031 | \$ 1,031 | \$ 997 | \$ 930 |
| Mailboxes & Signage Subtotal : | \$ 3,727 | \$ 3,727 | \$ 3,727 | \$ 3,727 | \$ 3,702 | \$ 3,667 | \$ 3,667 | \$ 3,558 | \$ 3,449 | \$ 3,449 | \$ 10,192 | \$ 10,192 | \$ 10,081 | \$ 10,081 | \$ 9,752 | \$ 9,099 |
| | | | | | | Paganya (| Potogony i Di | ainting 9 De | noizo | | | | | | | |
| | | | | | | Reserve | Category : Pa | amuny a re | pairs | 1 | | | | | | |
| Painting Interior Clubhouse | \$ 229 | \$ 229 | \$ 229 | \$ 229 | \$ 228 | \$ 226 | \$ 226 | \$ 219 | \$ 278 | \$ 278 | \$ 798 | \$ 798 | \$ 789 | \$ 789 | \$ 763 | \$ 712 |
| Painting Metal Unfunded | | | | | | | | | | | | | | | | |
| Repairs Concrete & Pavers | \$ 112 | \$ 112 | \$ 112 | \$ 112 | \$ 111 | \$ 110 | \$ 110 | \$ 107 | \$ 103 | \$ 103 | \$ 416 | \$ 416 | \$ 412 | \$ 412 | \$ 398 | \$ 372 |
| Painting & Repairs Subtotal : | \$ 341 | \$ 341 | \$ 341 | \$ 341 | \$ 339 | \$ 336 | \$ 336 | \$ 326 | \$ 381 | \$ 381 | \$ 1,214 | \$ 1,214 | \$ 1,201 | \$ 1,201 | \$ 1,161 | \$ 1,084 |
| | | | | | 1 | | | | 1 | 1 | | | | 1 | | |
| | | | | | | Re | serve Categ | ory : Pool | | | | | | | | |
| Chemical Controller Replacement | \$ 393 | \$ 393 | \$ 393 | \$ 393 | \$ 390 | \$ 386 | \$ 386 | \$ 375 | \$ 477 | \$ 477 | \$ 1,368 | \$ 1,368 | \$ 1,353 | \$ 1,353 | \$ 1,309 | \$ 1,221 |
| Filters Replacement | \$ 105 | \$ 105 | \$ 105 | \$ 105 | \$ 105 | \$ 104 | \$ 104 | \$ 101 | \$ 98 | \$ 98 | \$ 280 | \$ 280 | \$ 277 | \$ 277 | \$ 268 | \$ 416 |
| Kool-Deck Recoating | \$ 1,177 | \$ 1,177 | \$ 1,177 | \$ 1,177 | \$ 1,339 | \$ 1,326 | \$ 1,326 | \$ 1,287 | \$ 1,429 | \$ 1,429 | \$ 4,098 | \$ 4,098 | \$ 4,643 | \$ 4,643 | \$ 4,491 | \$ 4,191 |
| Kool-Deck Replacement | \$ 1,377 | \$ 1,377 | \$ 1,377 | \$ 1,377 | \$ 1,367 | \$ 1,355 | \$ 1,355 | \$ 1,314 | \$ 1,274 | \$ 1,274 | \$ 3,654 | \$ 3,654 | \$ 3,614 | \$ 3,614 | \$ 3,496 | \$ 3,262 |
| Pool Interior Refinishing | \$ 1,473 | \$ 1,473 | \$ 1,473 | \$ 1,473 | \$ 1,463 | \$ 1,450 | \$ 1,450 | \$ 1,406 | \$ 1,363 | \$ 1,363 | \$ 3,910 | \$ 3,910 | \$ 3,867 | \$ 3,867 | \$ 3,742 | \$ 5,810 |
| Pumps & Motors Replacement | \$ 228 | \$ 228 | \$ 228 | \$ 228 | \$ 226 | \$ 266 | \$ 266 | \$ 258 | \$ 250 | \$ 250 | \$ 849 | \$ 849 | \$ 840 | \$ 840 | \$ 812 | \$ 898 |

| | | | | | • | | | | | • | | | | | | |
|---|------------------|-----------|-----------|-----------|-----------|-----------|--------------|--------------|-----------|-------------|-----------|-------------|-----------|-----------|-----------|-----------|
| Item Name | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 |
| Pool Subtotal : | \$ 4,753 | \$ 4,753 | \$ 4,753 | \$ 4,753 | \$ 4,890 | \$ 4,887 | \$ 4,887 | \$ 4,741 | \$ 4,891 | \$ 4,891 | \$ 14,159 | \$ 14,159 | \$ 14,594 | \$ 14,594 | \$ 14,118 | \$ 15,798 |
| | | | | | | _ | | | | · · · · · · | | · · · · · · | | | | |
| | | | | | | Reserve | Category : | Refurbishme | ent | | | | | | | |
| Clubhouse Renovation | \$ 367 | \$ 367 | \$ 367 | \$ 367 | \$ 364 | \$ 361 | \$ 361 | \$ 350 | \$ 339 | \$ 339 | \$ 974 | \$ 974 | \$ 963 | \$ 963 | \$ 932 | \$ 869 |
| | | | | | | Rese | erve Categor | y : Roofing | | | | | | | | |
| Gutters & Downspouts Allowance | \$ 72 | \$ 72 | \$ 72 | \$ 72 | \$ 72 | \$ 71 | \$ 71 | \$ 69 | \$67 | \$67 | \$ 191 | \$ 191 | \$ 189 | \$ 189 | \$ 183 | \$ 171 |
| Metal Clubhouse Replacement | \$ 1,405 | \$ 1,405 | \$ 1,405 | \$ 1,405 | \$ 1,396 | \$ 1,383 | \$ 1,383 | \$ 1,341 | \$ 1,300 | \$ 1,300 | \$ 3,730 | \$ 3,730 | \$ 3,689 | \$ 3,689 | \$ 3,569 | \$ 3,330 |
| Roofing Subtotal : | \$ 1,477 | \$ 1,477 | \$ 1,477 | \$ 1,477 | \$ 1,468 | \$ 1,454 | \$ 1,454 | \$ 1,410 | \$ 1,367 | \$ 1,367 | \$ 3,921 | \$ 3,921 | \$ 3,878 | \$ 3,878 | \$ 3,752 | \$ 3,501 |
| | | | | | | D | 0-4 | 0 | -4- | | | | | | | |
| | | | | | | Reserve | Calegory : | Sports Coui | 15 | | | | | | | |
| Pickleball & Tennis Courts Resurfacing | \$ 479 | \$ 479 | \$ 479 | \$ 479 | \$ 476 | \$ 471 | \$ 471 | \$ 457 | \$ 443 | \$ 443 | \$ 1,786 | \$ 1,786 | \$ 1,767 | \$ 1,767 | \$ 1,709 | \$ 1,595 |
| | | | | | | Rese | erve Catego | ry : Tot Lot | | | | | | | | |
| Landing Surface Wood Mulch Unfunded | | | | | | | | | | | | | | | | |
| Nature Play Components Allowance | \$ 917 | \$ 917 | \$917 | \$ 917 | \$ 911 | \$ 902 | \$ 902 | \$ 875 | \$ 848 | \$ 848 | \$ 2,434 | \$ 2,434 | \$ 2,407 | \$ 2,407 | \$ 2,329 | \$ 2,173 |
| Play Platform Allowance | \$ 733 | \$ 733 | \$ 733 | \$ 733 | \$ 728 | \$ 722 | \$ 722 | \$ 700 | \$ 679 | \$ 679 | \$ 1,947 | \$ 1,947 | \$ 1,925 | \$ 1,925 | \$ 1,863 | \$ 1,738 |
| Swing-set Replacement | \$ 128 | \$ 128 | \$ 128 | \$ 128 | \$ 127 | \$ 126 | \$ 126 | \$ 123 | \$ 119 | \$ 119 | \$ 341 | \$ 341 | \$ 337 | \$ 337 | \$ 326 | \$ 304 |
| Tot Lot Subtotal : | \$ 1,778 | \$ 1,778 | \$ 1,778 | \$ 1,778 | \$ 1,766 | \$ 1,750 | \$ 1,750 | \$ 1,698 | \$ 1,646 | \$ 1,646 | \$ 4,722 | \$ 4,722 | \$ 4,669 | \$ 4,669 | \$ 4,518 | \$ 4,215 |
| Total Revenue : | \$ 24,813 | \$ 24,813 | \$ 24,813 | \$ 24,813 | \$ 24,813 | \$ 24,813 | \$ 24,813 | \$ 24,813 | \$ 24,813 | \$ 24,813 | \$ 76,750 | \$ 76,750 | \$ 76,750 | \$ 76,750 | \$ 76,750 | \$ 76,750 |

| <i>1</i> / N / | 00.40 | | | | - | | . I ununig | - | | 1 | 1 | 1 | 0050 | 0050 | 0054 |
|---|----------|----------|----------|----------|----------|---------------|---------------|----------------|----------|----------|----------|----------|----------|----------|--------|
| Item Name | 2040 | 2041 | 2042 | 2043 | 2044 | 2045 | 2046 | 2047 | 2048 | 2049 | 2050 | 2051 | 2052 | 2053 | 2054 |
| | | 1 | 1 | | Reserve | Category : Ap | opliances & E | lectronics | 1 | I | 1 | 1 | I | ī. | |
| Appliances Ice-maker Replacement | \$ 470 | \$ 470 | \$ 470 | \$ 625 | \$ 570 | \$ 551 | \$ 551 | \$ 551 | \$ 530 | \$ 437 | \$ 437 | \$ 437 | \$ 402 | \$ 402 | |
| Appliances Refrigerator- freezer Replacement | \$ 705 | \$ 705 | \$ 705 | \$ 938 | \$ 856 | \$ 827 | \$ 827 | \$ 827 | \$ 795 | \$ 656 | \$ 656 | \$ 656 | \$ 603 | \$ 603 | |
| Electronics Access Control System Allowance | \$ 1,810 | \$ 1,810 | \$ 1,810 | \$ 2,410 | \$ 2,604 | \$ 2,518 | \$ 2,518 | \$ 2,518 | \$ 2,419 | \$ 2,365 | \$ 2,365 | \$ 2,365 | \$ 2,177 | \$ 2,177 | |
| Electronics Fire Control Panel Replacement | \$ 309 | \$ 309 | \$ 309 | \$ 412 | \$ 375 | \$ 363 | \$ 363 | \$ 363 | \$ 523 | \$ 432 | \$ 432 | \$ 432 | \$ 397 | \$ 397 | \$ 629 |
| Electronics Observation Cameras Allowance | \$ 362 | \$ 362 | \$ 362 | \$ 482 | \$ 521 | \$ 504 | \$ 504 | \$ 504 | \$ 484 | \$ 473 | \$ 473 | \$ 473 | \$ 435 | \$ 435 | |
| Electronics Televisions Replacement | \$ 414 | \$ 414 | \$ 414 | \$ 552 | \$ 707 | \$ 683 | \$ 683 | \$ 683 | \$ 656 | \$ 542 | \$ 542 | \$ 542 | \$ 498 | \$ 498 | |
| Appliances & Electronics Subtotal : | \$ 4,070 | \$ 4,070 | \$ 4,070 | \$ 5,419 | \$ 5,633 | \$ 5,446 | \$ 5,446 | \$ 5,446 | \$ 5,407 | \$ 4,905 | \$ 4,905 | \$ 4,905 | \$ 4,512 | \$ 4,512 | \$ 629 |
| | | | | | | Reserve Cate | gory : Draina | ge & Irrigatio | n | | | | | | |
| Drainage Stormwater Management Allowance | \$ 3,356 | \$ 3,356 | \$ 3,356 | \$ 4,468 | \$ 4,073 | \$ 3,939 | \$ 3,939 | \$ 3,939 | \$ 3,784 | \$ 3,122 | \$ 3,122 | \$ 3,122 | \$ 2,872 | \$ 2,872 | |
| Irrigation Backflow Preventers Replacement | \$ 793 | \$ 793 | \$ 793 | \$ 1,055 | \$ 1,351 | \$ 1,306 | \$ 1,306 | \$ 1,306 | \$ 1,255 | \$ 1,035 | \$ 1,035 | \$ 1,035 | \$ 952 | \$ 952 | |
| Irrigation Controllers Allowance | \$ 343 | \$ 343 | \$ 343 | \$ 457 | \$ 417 | \$ 403 | \$ 403 | \$ 403 | \$ 582 | \$ 480 | \$ 480 | \$ 480 | \$ 441 | \$ 441 | \$ 699 |
| Drainage & Irrigation Subtotal : | \$ 4,492 | \$ 4,492 | \$ 4,492 | \$ 5,980 | \$ 5,841 | \$ 5,648 | \$ 5,648 | \$ 5,648 | \$ 5,621 | \$ 4,637 | \$ 4,637 | \$ 4,637 | \$ 4,265 | \$ 4,265 | \$ 699 |
| | | | | | | | | | | | | | | | |
| | | | | | | Reserve C | ategory : Fen | ces & Walls | 1 | | | 1 | | | |
| Fences Chain-link Replacement | \$ 1,224 | \$ 1,224 | \$ 1,224 | \$ 1,630 | \$ 1,486 | \$ 1,437 | \$ 1,437 | \$ 1,437 | \$ 1,381 | \$ 1,139 | \$ 1,139 | \$ 1,139 | \$ 1,048 | \$ 1,048 | |
| Fences Metal Replacement | \$ 1,599 | \$ 1,599 | \$ 1,599 | \$ 2,129 | \$ 1,941 | \$ 1,877 | \$ 1,877 | \$ 1,877 | \$ 1,803 | \$ 1,487 | \$ 1,487 | \$ 1,487 | \$ 1,369 | \$ 1,369 | |

2040 2041 2042 2043 2044 2045 2046 2047 2048 2049 2052 2053 2054 Item Name 2050 2051 Walls Masonry Perimeter \$ 541 \$ 541 \$ 541 \$ 720 \$ 922 \$ 891 \$ 891 \$ 891 \$ 856 \$ 706 \$ 706 \$ 706 \$ 650 \$ 650 Allowance \$ 4.479 Fences & Walls Subtotal \$ 3.364 \$ 3.364 \$ 3.364 \$ 4.349 \$ 4.205 \$ 4.205 \$ 4.205 \$ 4.040 \$ 3.332 \$ 3.332 \$ 3.332 \$ 3.067 \$ 3.067 Reserve Category : Furniture Clubhouse Interior \$ 1.071 \$ 1.071 \$ 1.071 \$ 1,426 \$ 1.825 \$ 1,765 \$ 1,765 \$ 1,765 \$ 1.696 \$ 1,399 \$ 1,399 \$ 1,399 \$ 1,287 \$ 1,287 Allowance Lifeguard Chair \$ 254 \$ 254 \$254 \$ 338 \$ 378 \$ 378 \$ 378 \$ 300 \$ 300 \$ 349 \$ 349 \$ 553 \$ 308 \$ 363 \$ 300 Replacement Park Allowance \$ 3,603 \$ 3,603 \$ 3,603 \$ 4,797 \$ 6,141 \$ 5,939 \$ 5,939 \$ 5,939 \$ 5,705 \$ 4,707 \$ 4,707 \$ 4,707 \$ 4,331 \$4,331 Pool Area Replacement \$ 4.005 \$ 4,005 \$ 4,005 \$ 5.332 \$4.861 \$ 5.963 \$ 5.963 \$ 5,963 \$ 5.728 \$4,726 \$ 4,726 \$ 4,726 \$ 5,515 \$ 5,515 \$ 8,730 Shade Covers \$ 5,453 \$ 5,453 \$ 5,453 \$ 7.260 \$ 6.618 \$ 6,401 \$ 6,401 \$ 6,401 \$ 8,067 \$ 6,655 \$ 6.655 \$ 6,655 \$ 6,124 \$6,124 \$ 9.694 Replacement \$ 14,386 \$ 14.386 \$ 14.386 \$ 19.153 \$ 19.753 \$ 20.446 \$ 20,446 \$ 21.559 \$ 17,787 \$ 17.787 \$ 17.787 \$ 17.606 \$ 17,606 \$ 18.977 Furniture Subtotal : \$ 20.446 Reserve Category : HVAC & Plumbing HVAC Air-Conditioners \$ 3,783 \$ 3,783 \$ 3,783 \$ 5,036 \$ 6,448 \$ 6,236 \$ 6,236 \$ 6,236 \$ 5,990 \$ 4,942 \$ 4,942 \$ 4,942 \$ 4,547 \$4,547 Replacement Plumbing Drinking \$ 253 \$ 126 \$ 126 \$ 126 \$ 168 \$ 153 \$ 148 \$ 148 \$ 148 \$ 143 \$ 275 \$ 275 \$ 275 \$ 253 \$ 400 Fountain Replacement Plumbing Firepit \$ 1.810 \$ 1.810 \$ 1.810 \$ 2.410 \$ 2.604 \$ 2.518 \$ 2.518 \$ 2.518 \$ 2.419 \$ 2.365 \$ 2.365 \$ 2.365 \$ 2,177 \$ 2,177 Assembly Allowance Plumbing Water Heater \$ 378 \$ 378 \$378 \$ 504 \$ 645 \$ 624 \$ 624 \$ 624 \$ 494 \$ 494 \$ 455 \$ 455 \$ 599 \$ 494 Replacement HVAC & Plumbing Subtotal \$ 6.097 \$ 6,097 \$ 6,097 \$ 8,118 \$ 9,850 \$ 9,526 \$ 9.526 \$ 9.526 \$ 9,151 \$ 8.076 \$ 8.076 \$ 8,076 \$ 7,432 \$ 7,432 \$ 400 Reserve Category : Lakes Lake Fountains \$ 6,409 \$ 8.532 \$ 8.824 \$ 6,409 \$ 6,409 \$ 7,778 \$ 9.541 \$ 9,541 \$ 9,541 \$ 9.165 \$ 7,561 \$ 7.561 \$ 7.561 \$ 8,824 \$ 13,968 Replacement Reserve Category : Lighting

Prepared by Great Boards, LLC

| | | Avaion | at Cypres | ss Commu | nity Assoc | ciation, inc | . Funding | Aajustea i | Revenue D | y Calendal | r Year - Co | ntinuea | | | |
|---|----------|----------|-----------|-----------|------------|--------------|----------------|--------------|-----------|------------|-------------|-----------|-----------|-----------|-----------|
| Item Name | 2040 | 2041 | 2042 | 2043 | 2044 | 2045 | 2046 | 2047 | 2048 | 2049 | 2050 | 2051 | 2052 | 2053 | 2054 |
| Bollard Fixtures Replacement | \$ 631 | \$ 631 | \$ 631 | \$ 840 | \$ 766 | \$ 741 | \$ 741 | \$ 741 | \$ 712 | \$ 1,372 | \$ 1,372 | \$ 1,372 | \$ 1,262 | \$ 1,262 | \$ 1,998 |
| Pole-Mounted Fixtures Replacement | \$ 1,124 | \$ 1,124 | \$ 1,124 | \$ 1,496 | \$ 1,916 | \$ 1,853 | \$ 1,853 | \$ 1,853 | \$ 1,780 | \$ 1,469 | \$ 1,469 | \$ 1,469 | \$ 1,351 | \$ 1,351 | |
| Lighting Subtotal : | \$ 1,755 | \$ 1,755 | \$ 1,755 | \$ 2,336 | \$ 2,682 | \$ 2,594 | \$ 2,594 | \$ 2,594 | \$ 2,492 | \$ 2,841 | \$ 2,841 | \$ 2,841 | \$ 2,613 | \$ 2,613 | \$ 1,998 |
| | | | | | | Reserve Cate | gory : Mailbo | xes & Sianaa | lê | | | | | | |
| Mailboxes Replacement | \$ 7,906 | \$ 7,906 | \$ 7,906 | \$ 10,526 | \$ 9,596 | \$ 9,280 | \$ 9,280 | \$ 9,280 | \$ 8,915 | \$ 17,187 | \$ 17,187 | \$ 17,187 | \$ 15,815 | \$ 15,815 | \$ 25,034 |
| Signage Entry Monument Refreshment Allowance | \$ 901 | \$ 901 | \$ 901 | \$ 1,199 | \$ 1,535 | \$ 1,485 | \$ 1,485 | \$ 1,485 | \$ 1,426 | \$ 1,177 | \$ 1,177 | \$ 1,177 | \$ 1,083 | \$ 1,083 | |
| Mailboxes & Signage Subtotal : | \$ 8,807 | \$ 8,807 | \$ 8,807 | \$ 11,725 | \$ 11,131 | \$ 10,765 | \$ 10,765 | \$ 10,765 | \$ 10,341 | \$ 18,364 | \$ 18,364 | \$ 18,364 | \$ 16,898 | \$ 16,898 | \$ 25,034 |
| | | | | | | D | | | | | | · | | | |
| | | | | | | Reserve Cat | egory : Painti | ng & Repairs | • | 1 | | 1 | 1 | | |
| Painting Interior Clubhouse | \$ 904 | \$ 904 | \$ 904 | \$ 1,204 | \$ 1,097 | \$ 1,061 | \$ 1,061 | \$ 1,061 | \$ 1,338 | \$ 1,104 | \$ 1,104 | \$ 1,104 | \$ 1,016 | \$ 1,016 | \$ 1,608 |
| Painting Metal Unfunded | | | | | | | | | | | | | | | |
| Repairs Concrete & Pavers | \$ 360 | \$ 360 | \$ 360 | \$ 479 | \$ 614 | \$ 593 | \$ 593 | \$ 593 | \$ 570 | \$ 470 | \$ 470 | \$ 470 | \$ 433 | \$ 433 | |
| Painting & Repairs Subtotal : | \$ 1,264 | \$ 1,264 | \$ 1,264 | \$ 1,683 | \$ 1,711 | \$ 1,654 | \$ 1,654 | \$ 1,654 | \$ 1,908 | \$ 1,574 | \$ 1,574 | \$ 1,574 | \$ 1,449 | \$ 1,449 | \$ 1,608 |
| | | | | | | | | _ / | 1 | 1 | 1 | | 1 | 1 | |
| | | | | | | Rese | rve Category | : Pool | 1 | | | | | | |
| Chemical Controller Replacement | \$ 1,551 | \$ 1,551 | \$ 1,551 | \$ 2,065 | \$ 1,882 | \$ 1,821 | \$ 1,821 | \$ 1,821 | \$ 2,294 | \$ 1,893 | \$ 1,893 | \$ 1,893 | \$ 1,741 | \$ 1,741 | \$ 2,757 |
| Filters Replacement | \$ 402 | \$ 402 | \$ 402 | \$ 536 | \$ 488 | \$ 472 | \$ 472 | \$ 472 | \$ 454 | \$ 374 | \$ 374 | \$ 374 | \$ 344 | \$ 344 | |
| Kool-Deck Recoating | \$ 4,647 | \$ 4,647 | \$ 4,647 | \$ 6,186 | \$ 6,459 | \$ 6,247 | \$ 6,247 | \$ 6,247 | \$ 6,875 | \$ 5,672 | \$ 5,672 | \$ 5,672 | \$ 5,978 | \$ 5,978 | \$ 9,462 |
| Kool-Deck Replacement | \$ 3,157 | \$ 3,157 | \$ 3,157 | \$ 4,204 | \$ 3,832 | \$ 3,706 | \$ 3,706 | \$ 3,706 | \$ 3,560 | \$ 2,937 | \$ 2,937 | \$ 2,937 | \$ 6,993 | \$ 6,993 | \$ 11,070 |
| Pool Interior Refinishing | \$ 5,623 | \$ 5,623 | \$ 5,623 | \$ 7,486 | \$ 6,824 | \$ 6,600 | \$ 6,600 | \$ 6,600 | \$ 6,340 | \$ 5,230 | \$ 5,230 | \$ 5,230 | \$ 4,813 | \$ 4,813 | |
| Pumps & Motors Replacement | \$ 869 | \$ 869 | \$ 869 | \$ 1,157 | \$ 1,250 | \$ 1,209 | \$ 1,209 | \$ 1,209 | \$ 1,161 | \$ 1,136 | \$ 1,136 | \$ 1,136 | \$ 1,045 | \$ 1,045 | |

| | | Avaion | at Cypres | ss Commu | nity Assoc | ation, inc | . Funaing . | Aajustea r | kevenue by | / Calendar | rear - Col | ntinuea | | | |
|---|-----------|-----------|-----------|------------|------------|------------|---------------|-------------|------------|------------|------------|------------|------------|------------|------------|
| Item Name | 2040 | 2041 | 2042 | 2043 | 2044 | 2045 | 2046 | 2047 | 2048 | 2049 | 2050 | 2051 | 2052 | 2053 | 2054 |
| Pool Subtotal : | \$ 16,249 | \$ 16,249 | \$ 16,249 | \$ 21,634 | \$ 20,735 | \$ 20,055 | \$ 20,055 | \$ 20,055 | \$ 20,684 | \$ 17,242 | \$ 17,242 | \$ 17,242 | \$ 20,914 | \$ 20,914 | \$ 23,289 |
| | | | | | | | | | | | | | | | |
| | | | | | | Reserve Ca | ategory : Ref | urbishment | | | | | | | |
| Clubhouse Renovation | \$ 841 | \$ 841 | \$ 841 | \$ 1,120 | \$ 1,021 | \$ 988 | \$ 988 | \$ 988 | \$ 949 | \$ 1,828 | \$ 1,828 | \$ 1,828 | \$ 1,682 | \$ 1,682 | \$ 2,663 |
| | | | | | | | | | | | | | | | |
| | | | | | | Reserv | e Category : | Roofing | | | | | | | |
| Gutters & Downspouts Allowance | \$ 165 | \$ 165 | \$ 165 | \$ 220 | \$ 200 | \$ 194 | \$ 194 | \$ 194 | \$ 186 | \$ 154 | \$ 154 | \$ 154 | \$ 141 | \$ 141 | |
| Metal Clubhouse Replacement | \$ 3,223 | \$ 3,223 | \$ 3,223 | \$ 4,291 | \$ 3,912 | \$ 3,783 | \$ 3,783 | \$ 3,783 | \$ 3,634 | \$ 2,998 | \$ 2,998 | \$ 2,998 | \$ 2,759 | \$ 2,759 | |
| Roofing Subtotal : | \$ 3,388 | \$ 3,388 | \$ 3,388 | \$ 4,511 | \$ 4,112 | \$ 3,977 | \$ 3,977 | \$ 3,977 | \$ 3,820 | \$ 3,152 | \$ 3,152 | \$ 3,152 | \$ 2,900 | \$ 2,900 | |
| | 1 | 1 | | | | | | | | | | | | | |
| | | | | | | Reserve C | ategory : Spo | orts Courts | | | | | | | |
| Pickleball & Tennis Courts Resurfacing | \$ 1,544 | \$ 1,544 | \$ 1,544 | \$ 2,055 | \$ 2,630 | \$ 2,544 | \$ 2,544 | \$ 2,544 | \$ 2,444 | \$ 2,016 | \$ 2,016 | \$ 2,016 | \$ 1,855 | \$ 1,855 | |
| | | | | | | | | | | | | | | | |
| | | | | | | Reserv | e Category : | Tot Lot | | | | | | | |
| Landing Surface Wood Mulch Unfunded | | | | | | | | | | | | | | | |
| Nature Play Components Allowance | \$ 2,103 | \$ 2,103 | \$ 2,103 | \$ 2,799 | \$ 2,552 | \$ 2,468 | \$ 2,468 | \$ 2,468 | \$ 2,371 | \$ 4,571 | \$ 4,571 | \$ 4,571 | \$ 4,206 | \$ 4,206 | \$ 6,658 |
| Play Platform Allowance | \$ 1,682 | \$ 1,682 | \$ 1,682 | \$ 2,239 | \$ 2,041 | \$ 1,974 | \$ 1,974 | \$ 1,974 | \$ 1,897 | \$ 3,657 | \$ 3,657 | \$ 3,657 | \$ 3,365 | \$ 3,365 | \$ 5,327 |
| Swing-set Replacement | \$ 294 | \$ 294 | \$ 294 | \$ 392 | \$ 357 | \$ 345 | \$ 345 | \$ 345 | \$ 332 | \$ 640 | \$ 640 | \$ 640 | \$ 589 | \$ 589 | \$ 933 |
| Tot Lot Subtotal : | \$ 4,079 | \$ 4,079 | \$ 4,079 | \$ 5,430 | \$ 4,950 | \$ 4,787 | \$ 4,787 | \$ 4,787 | \$ 4,600 | \$ 8,868 | \$ 8,868 | \$ 8,868 | \$ 8,160 | \$ 8,160 | \$ 12,918 |
| | | | | | | | | | | | | | | | |
| Total Revenue : | \$ 76,750 | \$ 76,750 | \$ 76,750 | \$ 102,181 | \$ 102,181 | \$ 102,181 | \$ 102,181 | \$ 102,181 | \$ 102,181 | \$ 102,181 | \$ 102,181 | \$ 102,181 | \$ 102,181 | \$ 102,181 | \$ 102,181 |

Avalon at Cypress Community Association, Inc. Funding Study - Expenses by Item and by Calendar Year

| Item Description | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | 2044 |
|--|------|------|------|------|----------|------|-----------|-----------|---------------|----------------|------------|----------|------------|-----------|-----------|------|------|------|-----------|-----------|
| | | I | 1 | 1 | | | 1 | Reserve | Category : A | ppliances & E | lectronics | | | | 1 | I | I | 1 | | |
| Appliances Ice-maker Replacement | | | | | | | | | | | | | | \$ 4,659 | | | | | | |
| Appliances Refrigerator-freezer Replacement | | | | | | | | | | | | | | \$ 6,989 | | | | | | |
| Electronics Access Control System Allowance | | | | | \$ 5,925 | | | | | \$ 7,021 | | | | \$ 8,320 | | | | | \$ 9,860 | |
| Electronics Fire Control Panel Replacement | | | | | | | | | | | | \$ 2,705 | | | | | | | | |
| Electronics Observation Cameras Allowance | | | | | \$ 1,185 | | | | | \$ 1,404 | | | | \$ 1,664 | | | | | \$ 1,972 | |
| Electronics Televisions Replacement | | | | | | | | | | \$ 3,230 | | | | | | | | | \$ 4,536 | |
| Category Subtotal : | | | | | \$ 7,110 | | | | | \$ 11,655 | | \$ 2,705 | | \$ 21,632 | | | | | \$ 16,368 | |
| | | | | | | | | Reserv | ve Category : | Drainage & Ir | rigation | | | | | | | | | |
| Drainage Stormwater Management Allowance | | | | | | | | | | | | | | \$ 33,282 | | | | | | |
| Irrigation Backflow Preventers Replacement | | | | | | | | | | \$ 6,179 | | | | | | | | | \$ 8,677 | |
| Irrigation Controllers Allowance | | | | | | | | | | | | \$ 3,006 | | | | | | | | |
| Category Subtotal : | | | | | | | | | | \$ 6,179 | | \$ 3,006 | | \$ 33,282 | | | | | \$ 8,677 | |
| | | | | | | | | Ree | erve Caterior | ry : Fences & | Nalle | | | | | | | | | |
| Fences Chain-link Replacement | | | | | | | | 100 | | | Tano | | | | | | | | | |
| Fences Metal Replacement | | | | | | | | | | | | | | | | | | | | |
| Walls Masonry Perimeter Allowance | | | | | | | | | | \$ 4,213 | | | | | | | | | \$ 5,916 | |
| Category Subtotal : | | | | | | | | | | \$ 4,213 | | | | | | | | | \$ 5,916 | |
| | | | | | | | | | Pasarya Cata | gory : Furnitu | 10 | | • • • | | | | | | | |
| Clubhouse Interior Allowance | | | | | | | | , | leserve cale | \$ 8,348 | 18 | | | | | | | | \$ 11,723 | |
| Lifeguard Chair Replacement | | | | | | | \$ 1,205 | | | \$ 0,040 | | | \$ 1,528 | | | | | | ¢ 11,720 | \$ 1,938 |
| Park Allowance | | | | | | | , | | | \$ 28,085 | | | + .,020 | | | | | | \$ 39,440 | , |
| Pool Area Replacement | | | | | | | \$ 19,024 | | | | | | \$ 24, 128 | | | | | | | \$ 30,601 |
| Shade Covers Replacement | | | | | | | | \$ 27,680 | | | | | | | \$ 36,318 | | | | | |
| Category Subtotal : | | | | | | | \$ 20,229 | \$ 27,680 | | \$ 36,433 | | | \$ 25,656 | | \$ 36,318 | | | | \$ 51,163 | \$ 32,539 |

| Item Description | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | 2044 |
|---|------|------|------|-----------|----------|------|-----------|-----------|---------------|-----------------|----------|-----------|------|-----------|-----------|-----------|------|------|------|-----------|-----------|
| | | 1 | | | J | | | Rese | rve Category | : HVAC & Plu | mbing | | I | | | 1 | | 1 | 1 | | |
| HVAC Air-Conditioners Replacement | | | | | | | | | | \$ 29,490 | | | | | | | | | | \$ 41,412 | |
| Plumbing Drinking Fountain Replacement | | | | | | | | | | | | | | | | | | | | | |
| Plumbing Firepit Assembly Allowance | | | | | \$ 5,925 | | | | | \$ 7,021 | | | | | \$ 8,320 | | | | | \$ 9,860 | |
| Plumbing Water Heater Replacement | | | | | | | | | | \$ 2,949 | | | | | | | | | | \$ 4,141 | |
| Category Subtotal : | | | | | \$ 5,925 | | | | | \$ 39,460 | | | | | \$ 8,320 | | | | | \$ 55,413 | |
| | | | | | | | | | Reserve Ca | tegory : Lakes | | | | | | | | | | | |
| Lake Fountains Replacement | | | | | | | \$ 30,439 | | | | | | | \$ 38,605 | | | | | | | \$ 48,962 |
| | | | | | | | | | Reserve Cate | egory : Lightin | a | | | | | | | | | | |
| Bollard Fixtures Replacement | | | | | | | | | | | , | | | | | | | | | | |
| Pole-Mounted Fixtures Replacement | | | | | | | | | | \$ 8,763 | | | | | | | | | | \$ 12,305 | |
| Category Subtotal : | | | | | | | | | | \$ 8,763 | | | | | | | | | | \$ 12,305 | |
| | | | | | | | | Reserv | ve Category : | Mailboxes & S | Sianaae | | | | | | | | | | |
| Mailboxes Replacement | | | | | | | | | | | | | | | | | | | | | |
| Signage Entry Monument Refreshment Allowance | | | | | | | | | | \$ 7,021 | | | | | | | | | | \$ 9,860 | |
| Category Subtotal : | | | | | | | | | | \$ 7,021 | | | | | | | | | | \$ 9,860 | |
| | | | | | | | | Rese | rve Categorv | : Painting & R | epairs | | | | | | | | | | |
| Painting Interior Clubhouse | | | | | | | | \$ 4,592 | | | | | | | | \$ 6,025 | | | | | |
| Painting Metal Unfunded | | | | | | | | | | | | | | | | | | | | | |
| Repairs Concrete & Pavers | | | | | | | | | | \$ 2,809 | | | | | | | | | | \$ 3,944 | |
| Category Subtotal : | | | | | | | | \$ 4,592 | | \$ 2,809 | | | | | | \$ 6,025 | | | | \$ 3,944 | |
| | | | | | | | | | Reserve Ca | ategory : Pool | | | | | | | | | | | |
| Chemical Controller Replacement | | | | | | | | \$ 7,872 | | | | | | | | \$ 10,329 | | | | | |
| Filters Replacement | | | | | | | | | | | | | | | \$ 3,994 | | | | | | |
| Kool-Deck Recoating | | | | \$ 11,747 | | | | \$ 13,455 | | | | \$ 15,413 | | | | \$ 17,655 | | | | \$ 20,223 | |
| Kool-Deck Replacement | | | | | | | | | | | | | | | | | | | | | |
| Pool Interior Refinishing | | | | | | | | | | | | | | | \$ 55,760 | | | | | | |

| | | | | 1 | | | | | | | | | | | | | 1 | | | 1 |
|------|------|-----------|---|---|---|---|---|---|---|---|---|---|--|--|--|--|--|--|--|--|
| 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | 2044 |
| | | | | \$ 2,844 | | | | | \$ 3,370 | | | | | \$ 3,994 | | | | | \$ 4,733 | |
| | | | \$ 11,747 | \$ 2,844 | | | \$ 21,327 | | \$ 3,370 | | \$ 15,413 | | | \$ 63,748 | \$ 27,984 | | | | \$ 24,956 | |
| | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | Res | erve Catego | ry : Refurbishr | nent | | | 1 | | | | - | | | |
| | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | Reserve Cat | egory : Roofing | 1 | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | |
| | | 1 | | | | 1 | | | | | | | 1 | | | | | | | 1 |
| | | | | | | | Rea | serve Catego | ory : Sports Co | urts | | | | | | | | | | |
| | | | | | | | | | \$ 12,032 | | | | | | | | | | \$ 16,896 | |
| | | | | | | | | | · · | | | | | | | | | | · · · | 1 |
| | | | | | | | | Reserve Cat | egory : Tot Lo | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | |
| | | | \$ 11,747 | \$ 15,879 | | 50 000 | \$ 53,600 | | * 404 000 | | | | | A 100 000 | | | | | A 005 100 | \$ 81,501 |
| | | 2024 2025 | 2024 2025 2026 Image: Constraint of the second se | Image: Sector of the sector | Image: Signal | Image: second | Image: Signal | Image: Section of the section of th | Image: state stat | Image: Second | Image: state stat | Image: Second | Image: state | Image: state s | Image: state s | Image: state s | Image: state s | Image: state s | Image: state s | Image: stand s |

| Item Description | 2045 | 2046 | 2047 | 2048 | 2049 | 2050 | 2051 | 2052 | 2053 | 2054 |
|--|------|------|---------------|------------------|---------------|------|-----------|------|------------|------|
| | | Re | eserve Catego | ry : Appliance | s & Electror | nics | | | | |
| Appliances Ice-maker Replacement | | | | | | | | | \$ 7,754 | |
| Appliances Refrigerator-freezer Replacement | | | | | | | | | \$ 11,631 | |
| Electronics Access Control System Allowance | | | | \$ 11,684 | | | | | \$ 13,846 | |
| Electronics Fire Control Panel Replacement | | | \$ 4,066 | | | | | | | |
| Electronics Observation Cameras Allowance | | | | \$ <i>2,33</i> 7 | | | | | \$ 2,769 | |
| Electronics Televisions Replacement | | | | | | | | | \$ 6,369 | |
| Category Subtotal : | | | \$ 4,066 | \$ 14,021 | | | | | \$ 42,369 | |
| | | | Reserve Cate | orv : Drainao | e & Irriaatio | n | | | | |
| Drainage Stormwater Management Allowance | | | | | _ | | | | \$ 55,384 | |
| Irrigation Backflow Preventers Replacement | | | | | | | | | \$ 12,184 | |
| Irrigation Controllers Allowance | | | \$ 4,518 | | | | | | | |
| Category Subtotal : | | | \$ 4,518 | | | | | | \$ 67,568 | |
| | | | Reserve Ca | ategory : Fenc | es & Walls | | | | | |
| Fences Chain-link Replacement | | | | | | | | | \$ 41,040 | |
| Fences Metal Replacement | | | | | | | | | \$ 53,584 | |
| Walls Masonry Perimeter Allowance | | | | | | | | | \$ 8,308 | |
| Category Subtotal : | | | | | | | | : | \$ 102,932 | |
| | | | Reserve | Category : Fi | urniture | | | | | |
| Clubhouse Interior Allowance | | | 1.000/76 | . catogory . I t | | | | | \$ 16,463 | |
| Lifeguard Chair Replacement | | | | | | | \$ 2,458 | | | |
| Park Allowance | | | | | | | | | \$ 55,384 | |
| Pool Area Replacement | | | | | | | \$ 38,811 | | | |
| Shade Covers Replacement | | | \$ 47,652 | | | | | | | |
| Category Subtotal : | | | \$ 47,652 | | | | \$ 41,269 | | \$ 71,847 | |

| Item Description | 2045 | 2046 | 2047 | 2048 | 2049 | 2050 | 2051 | 2052 | 2053 | 2054 |
|---|------|------|--------------|----------------|--------------|------|-----------|------|------------|------|
| | | | Reserve Cat | tegory : HVAC | & Plumbing | | | | | |
| HVAC Air-Conditioners Replacement | | | | | | | | | \$ 58, 153 | |
| Plumbing Drinking Fountain Replacement | | | | \$ 3,505 | | | | | | |
| Plumbing Firepit Assembly Allowance | | | | \$ 11,684 | | | | | \$ 13,846 | |
| Plumbing Water Heater Replacement | | | | | | | | | \$ 5,815 | |
| Category Subtotal : | | | | \$ 15,189 | | | | | \$ 77,814 | |
| | | | Reser | ve Category : | Lakes | | | | | |
| Lake Fountains Replacement | | | | | | | \$ 62,098 | | | |
| | | | Reserv | e Category : I | Lighting | | | | | |
| Bollard Fixtures Replacement | | | | \$ 17,526 | | | | | | |
| Pole-Mounted Fixtures Replacement | | | | | | | | | \$ 17,280 | |
| Category Subtotal : | | | | \$ 17,526 | | | | | \$ 17,280 | |
| | | | Reserve Cate | gory : Mailbo | xes & Signag | e | | | | |
| Mailboxes Replacement | | | | \$ 219,663 | | | | | | |
| Signage Entry Monument Refreshment Allowance | | | | | | | | | \$ 13,846 | |
| Category Subtotal : | | | | \$ 219,663 | | | | | \$ 13,846 | |
| | | | Reserve Cat | egory : Painti | ng & Repairs | | | | | |
| Painting Interior Clubhouse | | | \$ 7,906 | | | | | | | |
| Painting Metal Unfunded | | | | | | | | | | |
| Repairs Concrete & Pavers | | | | | | | | | \$ 5,538 | |
| Category Subtotal : | | | \$ 7,906 | | | | | | \$ 5,538 | |
| | | | Rese | rve Category | : Pool | | | | | |
| Chemical Controller Replacement | | | \$ 13,553 | | | | | | | |
| Filters Replacement | | | | | | | | | \$ 6,646 | |
| Kool-Deck Recoating | | | \$ 23,164 | | | | \$ 26,534 | | | |
| Kool-Deck Replacement | | | | | | | \$ 98,554 | | | |
| Pool Interior Refinishing | | | | | | | | | \$ 92,790 | |

| | | | | | | | | | - | |
|---|------|------|------------|----------------|-------------|------|------------|------|------------|------|
| Item Description | 2045 | 2046 | 2047 | 2048 | 2049 | 2050 | 2051 | 2052 | 2053 | 2054 |
| Pumps & Motors Replacement | | | | \$ 5,608 | | | | | \$ 6,646 | |
| Category Subtotal : | | | \$ 36,717 | \$ 5,608 | | | \$ 125,088 | | \$ 106,082 | |
| | | | | | | | | | | |
| | | | Reserve C | ategory : Ref | urbishment | | | | | |
| Clubhouse Renovation | | | | \$ 23,368 | | | | | | |
| | | | | | | | | | | |
| | | | Reserv | e Category : I | Roofing | | | | | |
| Gutters & Downspouts Allowance | | | | | | | | | \$ 5,538 | |
| Metal Clubhouse Replacement | | | | | | | | | \$ 107,992 | |
| Category Subtotal : | | | | | | | | | \$ 113,530 | |
| | | | | | | | | | | |
| | | | Reserve C | Category : Spo | orts Courts | | | | | |
| Pickleball & Tennis Courts Resurfacing | | | | | | | | | \$ 23,726 | |
| | | | | | | | | | | |
| | | | Reserv | /e Category : | Tot Lot | | | | | |
| Landing Surface Wood Mulch Unfunded | | | | | | | | | | |
| Nature Play Components Allowance | | | | \$ 58,421 | | | | | | |
| Play Platform Allowance | | | | \$ 46,737 | | | | | | |
| Swing-set Replacement | | | | \$ 8,179 | | | | | | |
| Category Subtotal : | | | | \$ 113,337 | | | | | | |
| | | | | | | | | | | |
| Expense Totals : | | | \$ 100,859 | \$ 408,713 | | | \$ 228,455 | | \$ 642,533 | |



30-Year Expense Summary

| Year | Category | Item Name | Expense |
|------|---|---|------------------|
| 2027 | Pool | Kool-Deck Recoating | \$ 11,747 |
| | | 2027 Annual Expense T | otal = \$ 11,747 |
| | Appliances & Electronics | Electronics Access Control System Allowance | \$ 5,925 |
| | | Electronics Observation Cameras Allowance | \$ 1,185 |
| 2028 | Appliances & Electronics Subtotal = \$ 7,110.00 | | |
| | HVAC & Plumbing | Plumbing Firepit Assembly Allowance | \$ 5,925 |
| | Pool | Pumps & Motors Replacement | \$ 2,844 |
| | | 2028 Annual Expense T | otal = \$ 15,879 |
| | Furniture | Lifeguard Chair Replacement | \$ 1,205 |
| 0000 | | Pool Area Replacement | \$ 19,024 |
| 2030 | Furniture Subtotal = \$ 20,229.00 | | |
| | Lakes | Lake Fountains Replacement | \$ 30,439 |
| | 1 | 2030 Annual Expense T | otal = \$ 50,668 |
| | Furniture | Shade Covers Replacement | \$ 27,680 |
| | Painting & Repairs | Painting Interior Clubhouse | \$ 4,592 |
| 2031 | Pool | Chemical Controller Replacement | \$ 7,872 |
| | | Kool-Deck Recoating | \$ 13,455 |
| | | Pool Subtotal = \$ 21,327.00 | |
| | 1 | 2031 Annual Expense T | otal = \$ 53,599 |
| 2033 | Appliances & Electronics | Electronics Access Control System Allowance | \$ 7,021 |

Prepared by Great Boards, LLC

| Year | Category | Item Name | Expense |
|------|--|--|----------------------|
| | Appliances & Electronics | Electronics Observation Cameras Allowance | \$ 1,40 ⁴ |
| | | Electronics Televisions Replacement | \$ 3,23 |
| | Appliances & Electronics Subtotal = \$ 11,655.00 | | |
| | Drainage & Irrigation | Irrigation Backflow Preventers Replacement | \$ 6,17 |
| | Fences & Walls | Walls Masonry Perimeter Allowance | \$ 4,21 |
| | Furniture | Clubhouse Interior Allowance | \$ 8,34 |
| | Furniture | Park Allowance | \$ 28,08 |
| | | Furniture Subtotal = \$ 36,433.00 | |
| 2033 | | HVAC Air-Conditioners Replacement | \$ 29,49 |
| | HVAC & Plumbing | Plumbing Firepit Assembly Allowance | \$ 7,02 |
| | | Plumbing Water Heater Replacement | \$ 2,949 |
| | HVAC & Plumbing Subtotal = \$ 39,460.00 | | |
| | Lighting | Pole-Mounted Fixtures Replacement | \$ 8,76 |
| | Mailboxes & Signage | Signage Entry Monument Refreshment Allowance | \$ 7,02 |
| | Painting & Repairs | Repairs Concrete & Pavers | \$ 2,80 |
| | Pool | Pumps & Motors Replacement | \$ 3,37 |
| | Sports Courts | Pickleball & Tennis Courts Resurfacing | \$ 12,03 |
| | | 2033 Annual Expense To | tal = \$ 131,93 |
| | Appliances & Electronics | Electronics Fire Control Panel Replacement | \$ 2,70 |
| 2035 | Drainage & Irrigation | Irrigation Controllers Allowance | \$ 3,00 |
| | Pool | Kool-Deck Recoating | \$ 15,41 |
| | | 2035 Annual Expense T | otal = \$ 21,12 |
| | Furniture | Lifeguard Chair Replacement | \$ 1,52 |
| | | Pool Area Replacement | \$ 24,12 |
| 2037 | Furniture Subtotal = \$ 25,656.00 | | |
| | Lakes | Lake Fountains Replacement | \$ 38,60 |
| | | 2037 Annual Expense T | otal = \$ 64,26 |
| 2038 | Appliances & Electronics | Appliances Ice-maker Replacement | \$ 4,65 |
| | | Appliances Refrigerator-freezer Replacement | \$ 6,98 |

Prepared by Great Boards, LLC

| Year | Category | Item Name | Expense |
|------|--|---|-------------------|
| | Appliances & Electronics | Electronics Access Control System Allowance | \$ 8,320 |
| | | Electronics Observation Cameras Allowance | \$ 1,664 |
| | Appliances & Electronics Subtotal = \$ 21,632.00 | | |
| | Drainage & Irrigation | Drainage Stormwater Management Allowance | \$ 33,282 |
| 2038 | HVAC & Plumbing | Plumbing Firepit Assembly Allowance | \$ 8,320 |
| | | Filters Replacement | \$ 3,994 |
| | Pool | Pool Interior Refinishing | \$ 55,760 |
| | | Pumps & Motors Replacement | \$ 3,994 |
| | | Pool Subtotal = \$ 63,748.00 | |
| | | 2038 Annual Expense T | otal = \$ 126,982 |
| | Furniture | Shade Covers Replacement | \$ 36,318 |
| | Painting & Repairs | Painting Interior Clubhouse | \$ 6,025 |
| 2039 | | Chemical Controller Replacement | \$ 10,329 |
| | Pool | Kool-Deck Recoating | \$ 17,655 |
| | Pool Subtotal = \$ 27,984.00 | | |
| | | 2039 Annual Expense | Total = \$ 70,327 |
| | | Electronics Access Control System Allowance | \$ 9,860 |
| | Appliances & Electronics | Electronics Observation Cameras Allowance | \$ 1,972 |
| | | Electronics Televisions Replacement | \$ 4,536 |
| | Appliances & Electronics Subtotal = \$ 16,368.00 | | |
| | Drainage & Irrigation | Irrigation Backflow Preventers Replacement | \$ 8,677 |
| | Fences & Walls | Walls Masonry Perimeter Allowance | \$ 5,916 |
| 2043 | | Clubhouse Interior Allowance | \$ 11,723 |
| | Furniture | Park Allowance | \$ 39,440 |
| | Furniture Subtotal = \$ 51,163.00 | | |
| | HVAC & Plumbing | HVAC Air-Conditioners Replacement | \$ 41,412 |
| | | Plumbing Firepit Assembly Allowance | \$ 9,860 |
| | | Plumbing Water Heater Replacement | \$ 4,141 |
| | | HVAC & Plumbing Subtotal = \$ 55,413.00 | |

Prepared by Great Boards, LLC

| Year | Category | Item Name | Expense |
|------|--|--|-----------------------|
| | Lighting | Pole-Mounted Fixtures Replacement | \$ 12,305 |
| | Mailboxes & Signage | Signage Entry Monument Refreshment Allowance | \$ 9,860 |
| | Painting & Repairs | Repairs Concrete & Pavers | \$ 3,944 |
| 2043 | | Kool-Deck Recoating | \$ 20,223 |
| | Pool | Pumps & Motors Replacement | \$ 4,733 |
| | Pool Subtotal = \$ 24,956.00 | | |
| | Sports Courts | Pickleball & Tennis Courts Resurfacing | \$ 16,896 |
| | | 2043 Annual Expense To | tal = \$ 205,498 |
| | _ | Lifeguard Chair Replacement | \$ 1,938 |
| | Furniture | Pool Area Replacement | \$ 30,60 ² |
| 2044 | Furniture Subtotal = \$ 32,539.00 | | |
| | Lakes | Lake Fountains Replacement | \$ 48,962 |
| | | 2044 Annual Expense T | otal = \$ 81,50 |
| | Appliances & Electronics | Electronics Fire Control Panel Replacement | \$ 4,066 |
| | Drainage & Irrigation | Irrigation Controllers Allowance | \$ 4,518 |
| | Furniture | Shade Covers Replacement | \$ 47,652 |
| 2047 | Painting & Repairs | Painting Interior Clubhouse | \$ 7,906 |
| | Pool | Chemical Controller Replacement | \$ 13,553 |
| | | Kool-Deck Recoating | \$ 23,164 |
| | Pool Subtotal = \$ 36,717.00 | | |
| | | 2047 Annual Expense To | tal = \$ 100,859 |
| | | Electronics Access Control System Allowance | \$ 11,684 |
| | Appliances & Electronics | Electronics Observation Cameras Allowance | \$ 2,337 |
| | Appliances & Electronics Subtotal = \$ 14,021.00 | | |
| | HVAC & Plumbing | Plumbing Drinking Fountain Replacement | \$ 3,505 |
| 2048 | | Plumbing Firepit Assembly Allowance | \$ 11,684 |
| | HVAC & Plumbing Subtotal = \$ 15,189.00 | | |
| | Lighting | Bollard Fixtures Replacement | \$ 17,526 |
| | Mailboxes & Signage | Mailboxes Replacement | \$ 219,663 |

Prepared by Great Boards, LLC

| Year | Category | Item Name | Expense |
|------|--|---|-----------------------|
| 2048 | Pool | Pumps & Motors Replacement | \$ 5,608 |
| | Refurbishment | Clubhouse Renovation | \$ 23,368 |
| | | Nature Play Components Allowance | \$ 58,421 |
| | Tot Lot | Play Platform Allowance | \$ 46,737 |
| | | Swing-set Replacement | \$ 8,179 |
| | Tot Lot Subtotal = \$ 113,337.00 | | |
| | | 2048 Annual Expense Tot | al = \$ 408,712 |
| | | Lifeguard Chair Replacement | \$ 2,458 |
| | Furniture | Pool Area Replacement | \$ 38,811 |
| | | Furniture Subtotal = \$ 41,269.00 | |
| 2051 | Lakes | Lake Fountains Replacement | \$ 62,098 |
| | | Kool-Deck Recoating | \$ 26,534 |
| | Pool | Kool-Deck Replacement | \$ 98,554 |
| | Pool Subtotal = \$ 125,088.00 | | |
| | | 2051 Annual Expense Tot | al = \$ 228,45 |
| | | Appliances Ice-maker Replacement | \$ 7,754 |
| | Appliances & Electronics | Appliances Refrigerator-freezer Replacement | \$ 11,63 ⁻ |
| | | Electronics Access Control System Allowance | \$ 13,84 |
| | | Electronics Observation Cameras Allowance | \$ 2,76 |
| | | Electronics Televisions Replacement | \$ 6,36 |
| | Appliances & Electronics Subtotal = \$ 42,369.00 | | |
| 2053 | Drainage & Invigation | Drainage Stormwater Management Allowance | \$ 55,38 [,] |
| 2053 | Drainage & Irrigation | Irrigation Backflow Preventers Replacement | \$ 12,18 |
| | Drainage & Irrigation Subtotal = \$ 67,568.00 | | |
| | Fences & Walls | Fences Chain-link Replacement | \$ 41,04 |
| | | Fences Metal Replacement | \$ 53,58 |
| | | Walls Masonry Perimeter Allowance | \$ 8,30 |
| | | Fences & Walls Subtotal = \$ 102,932.00 | |
| | Furniture | Clubhouse Interior Allowance | \$ 16,46 |

Prepared by Great Boards, LLC

| Year | Category | Item Name | Expense |
|------|---|--|-----------------|
| | Furniture | Park Allowance | \$ 55,384 |
| | Furniture Subtotal = \$ 71,847.00 | | |
| | HVAC & Plumbing | HVAC Air-Conditioners Replacement | \$ 58,153 |
| | | Plumbing Firepit Assembly Allowance | \$ 13,846 |
| | | Plumbing Water Heater Replacement | \$ 5,815 |
| | HVAC & Plumbing Subtotal = \$ 77,814.00 | | |
| | Lighting | Pole-Mounted Fixtures Replacement | \$ 17,280 |
| | Mailboxes & Signage | Signage Entry Monument Refreshment Allowance | \$ 13,846 |
| 2053 | Painting & Repairs | Repairs Concrete & Pavers | \$ 5,538 |
| | Pool | Filters Replacement | \$ 6,646 |
| | | Pool Interior Refinishing | \$ 92,790 |
| | | Pumps & Motors Replacement | \$ 6,646 |
| | Pool Subtotal = \$ 106,082.00 | | |
| | Roofing | Gutters & Downspouts Allowance | \$ 5,538 |
| | | Metal Clubhouse Replacement | \$ 107,992 |
| | Roofing Subtotal = \$ 113,530.00 | | |
| | Sports Courts | Pickleball & Tennis Courts Resurfacing | \$ 23,726 |
| | | 2053 Annual Expense Tot | al = \$ 642,532 |